LAND CORNER RECORDATION CERTIFICATE

For corners in

Filing Requirement of Act 74, Mich. P.A. 1970 MAY 9 11 03 AM '95

Charles P. Garlock, in a field survey on	
Charles P. Garlock, in a field survey on April 28 tg 95 charles peril that under requirements of PA.74 Michigan PA. of 1970, the corner points mentioned of hierarchy derify that under requirements of PA.74 Michigan PA. of 1970, the corner points mentioned of the principle of the United States Department of the Interior, Bureau of Land Banagement of by Adecee of a Court of Law Androf Intal the corner points mentioned in lines 3, 4 and 5 bove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Docree of a out of Law setablished, re-established, monumented, re-monumented, recovered found as surpressed below: OTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. Description of original monument and accessories and/or subsequent restoration: GLO survey dated April 15, 1825 by S sibley DS GLO witnesses: W012-N47W-391ks W016-S45%W-35 1ks Additional historistal data on rear of sheet Description of corner evidence found and/or method applied in restoring or reestablishing corner. Found Railroad spike Description of monument for corner and accessories established to perpetuate locating the position of the corner: M.6. Fact 174 corner Section 13 T2N-R4F, Marion Twp, Liv. Co. MI, reset RR spike with	er
Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found Railroad spike CARAN AND THE CONTROL OF THE CONTRO	13-4-25-36-36-
Description of monument for corner and accessories established to perpetuate locating the position of the corner: M.6. Fact 1/4 corner Section 13 T2N-R4E. Marion Two. Liv. Co. MI, reset RR spike with	
Description of monument for corner and accessories established to perpetuate locating the position of the corner: M.6: Fact 1/4 corner Section 13 T2N-R4E. Marion Two. Liv. Co. MI, reset RR spike with	
Description of monument for corner and accessories established to perpetuate locating the position of the corner:	
ML6. Fact 1/4 corner Section 13 T2N-R4E. Marion Two. Liv. Co. MI, reset RR spike with	
1 1/4" X 36" breakaway I. Pipe with Liv. Co. Remontances cap on top at -0.5' N35E-50.37'-sp & tag W/s U. Pole N30W-56.14'-sp & tag East/s 40" oak S75W-24.50'-sp & tag E/s 38" oak S20E-124.97'-sp & tag NE/s 18" Hickory East-2'±-c/l Fisk Rd. North-337.49'-W 1/4 cor. Sec. 18 T2N-R5E Date April 29, 1995	
TIVEYOR'S MICHIGAN LICENSE NO. 14762	N. 28, 197 NY 14, 197

CORNER SUMMARY

M-6: E 1/4 COR. SECTION 13, T2N-R4E, MARION TWP., LIV. CO. MI

GLO SURVEY DATED APRIL 15, 1825 BY S SIBLEY, NONE OF THE GLO WITNESSES REMAIN.

M BULLOCK WITNESSED THE CORNER IN 1904, NONE OF THE WITNESSES REMAIN. NEXT KNOWN ACTIVITY WAS IN 1980 WHEN I FOUND A RR SPIKE ABOUT 2 FT. WEST OF THE CENTERLINE OF A GRAVEL ROAD. SINCE THAT TIME ALBRIGHT, DESINE, THOMPSON AND MYSELF HAVE FOUND THE RR SPIKE AND ALL OF OUR WITNESSES CHECK. NO OCCUPATION TO THE WEST UNTIL 1/4 MILE AND THEN IT LINES WITH A FENCE LINE TO THE CENTER OF SAID SECTION. GLO DISTANCE NORTH TO THE GENOA CORNER IS 322.41 FEET AND IT MEASURES 337.49 FEET TO AN IRON AND OCCUPATION TO THE EAST. MEASURE NORTH TO THE NE COR. IS: 2636.71 FT. = DESINE AND MYSELF; SOUTH TO THE SE COR.: 2645.99 FT = THOMPSON, 2645.78 = DESINE AND 2645.80 = MYSELF. MEASURE WEST TO THE CTR. OF SECTION: 2525.08 FT. = DET. EDISON & ALBRIGHT; 2524.48 = DESINE AND 2524.77 = MYSELF. TWO ACT 74'S ARE RECORDED AND ONE ACT 132. OVERHANGING TREES MAKE THIS A POOR GPS STATION.

CHARLES E GARLOCK

PS14762



コメー ナビ

250