## LAND CORNER RECORDATION CERTIFICATE

For corners in	Filing R	equirement of Act 74,	Mich. P.A. 1970	)					
	and dis	0		. 1001				_	
(County)	ocated in:	Corner Code #		1998	NUV	IU P	1: 2	! <b>D</b>	
1. Public Land Survey	T <u>4N</u> R <u>3E</u> T R T R T R	<u>D-13</u>		K!	enste Rusto,	HAYILA R OF DE N COUN 1843	EDG	•	
2. Property Controlling S_ in Section S_ 3. Miscellaneous S_ Property in Sec. S_	T R R T R R			Registe		. C . <b>#</b> 5 eds Sta		-ile Nu	mber
4. Lot No, Recorded F	Plat			3 D G					
5. Private Claims				2 6	D E	F G		J K	
		1		3	<del>-  </del> -		<u> </u>	$\dashv$	<del>                                     </del>
I, <u>DARRELL HUGHES</u> , in a requirements of P.A. 74, Michigan P.A. conformance with regulations and rules to United States Department of the Interior, that the corner points mentioned in lines Board of Land Surveyors or by a Decrecovered, found as expressed below:	of 1970, the corner pointherefore as required in the Bureau of Land Manages 3, 4 and 5 above were	ints mentioned in lines 1 and he current manual of survey in tement or by a decree of a Cou in conformance with the rules	2 above were in astructions of the just of Law and for s of the Michigan d, monumented,	4 7 5 6 -18 7 8 -19	17-20-	9-1-6-1-6-1-6-1-6-1-6-1-6-1-6-1-6-1-6-1-	-101522	-11	—12 —13 —24
NOTE: Not more than 2 corners, a	I in the same town and	d range, may be recorded		9	_ -				
on this certificate.				10 30	-2'9	2'8  	-27-	—26  	2 <sup>1</sup> 5-
•		•		11 31-	_32	-33-	_34	35	—36
A. Description of original monumer GLO: 1825 Maple 6", Nor Elm 7", North	nt and accessories ar th 39 degrees 55 degrees Ea	West, 8 links	ion:			ONWAY			
B. Description of corner evidence Found 1-1/4" iron pi project.					Remoni	umenta	ıtion		
*Additional descript:	ions and histo	orical information	n on back of	this s	heet.				
C. Description of monument for con	rner and accessories	established to perpetuate	locating the position	on of the c	orner:				
D-13, T4N, R3E, 36" iron pipe, Monumentation Cofaithful perpetua 090 DEG. 166.59' 270 DEG. 4.67' FD 360 DEG. 57.55' FO 045 DEG. 30.52' FO 090 DEG. 29.27' FO	affixed with rner, P.S. tion of the D-1, T3N, R3 NAIL/REMOND, NAIL/REM	h 2" dia. bras 14762, and position of t 3E, HANDY. N.TAG S/S 6" E ON.TAG E/S 15" ON TAG W/S TRI	s cap, sta is accepte he origina LM. ASH. PLE 12" MA	imped das dcor:	"Li	luas	ton	Co	•
Signed by	1 Hab	5	Date Octo	ober 24	, 199	6	, <sub>10</sub>	· · · //	
Surveyor's Michigan License No	19834						11.7 ° '' 11.0		6

## CONWAY TOWNSHIP, T4N, R3E

D-13, THE SOUTH 1/4 CORNER OF SECTION 32, ON THE TOWN LINE.

FIELD: 6-21-1996 DARRELL D. HUGHES AND ASSOCIATES, FOWLERVILLE.

Found 1-1/4" Iron pipe in E/W fence line as set by Garlock in 1995. As stated in Garlock's Act 74, "Set iron pipe at half distance between C-13 and E-13 and on E/W fence line." P.8C Garlock, then being the monumenting surveyor for Conway Township, had to resolve the position of E-13. By running out the South township line West to C-13. No evidence of this corner ever being used by any surveyor. No occupation North. An 1/2" iron was found by Garlock 18.62' West of this position, in the E/W fence line. The North 1/4 corner of Sec. 5 (D-1) Handy, as proposed by Garlock, See drawing P.8C, is 166.59° East (computed GLO= 169.95°) I recommend, to the peer group, the acceptance of the method used by Garlock to establish this corner. Our measures West to C-13 agree and Garlock's witness' check. C-13 to G-13, as measured and shown by Garlock (bottom center page 8-B.....10539.3' divided by 4 = 2634.825°), is further weight for the position of this corner.

1825 Sylvester Sibley, Deputy U.S. Surveyor, "West on the South boundary of Sec. 32, 40.00 chains, set 1/4 section post". P.7-7A

1995 Garlock's 1995 remonumentation measures and notes for the establishment of E-13. P.8-8B

1995 Garlock sets D-13 and files Act 74. P.8C