

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43-44 N. R. 7W


Macinac COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Secs. 1-36 on Township Line

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 3/17/64

WITNESSES TO CORNER..... 5" B. Spruce ($\frac{1}{2}$ S MBT) N81°W 44 Lks.



7" B. Spruce ($\frac{1}{2}$ S MBT) S42°E 36½ Lks.

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was re-established midway and on line between two Section Corners.
Found old blazes on line to East but no evidence of Original Corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler
BILLY D. BUCKLER
REGISTERED LAND SURVEYOR

DATE 8/4/1964