Cons. 4047 Rev. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 42-43 H.R. 8 W

		Mackinac	COUNTY
DESCRIPTION OF CORNER _	Section Corner common to S	ecs. 1 1-2-35-36	
CORNER MONUMENT 1" II	on Pipe with 4" Brass Cap		<u>.</u>
DATE MONUMENT PLACED AN	D WITHESSED 11/6/63 with Ed	. Bckart, Assit. Forester	
WITHESSES TO CORNER	10" Cedar Stump (S2 MBT),	H 24 H, 68 Lks.	
N	12° Gedar Stump (\$36 EBT)	, S 76° W, 57 Dks.	
42-8	Corner lies in old Beaver	Dam and 10 Iks. North of S	Sand Ridge
CIRCLE COMER REGISTERS	AND		

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was remestablished by Single Proportionate Measure from Corners 1/2 mile Mast and 1 mile West. Found no evidence of Original Corner.

SURVEYOR'S SEAL

SIGNED BILLY D. Buckler DATE 10/19/1964