LAND COMMEN RECOMBATION CENTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Mackinac Co.

FOR STATE AND UNITED STATES ACENCIES:

5

2 Corners.

FOR CORNERS OF -:	LOCATED IN-:	ļ	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY	T S., R	E. W.		
2. PROPERTY CONTROLL-18 ING IN SECTION————————————————————————————————————	,T43	11 X:	1, 15	
3. MISCELLANEOUS PROPERTY IN SECTION	,T	E.		
4. LOT NO, RECO	ORDED PLAT			
5. PRIVATE CLAIMS	<u>-</u>			REGISTER OF DEEDS STAMP AND FILING NUMBER
David E. Babbitt	, do h	ereby ce	rtify that under requirements o	of P.A. 74, Michigan P.A. of 1970,
re-established, monumented, re- and rules therefore as required i Bureau of Land Management or and 5 above were, in a field surve	monumented, recovere in the current manual by a decree of a court ey on	ed or res of survey t of law.	tored as expressed below and y instructions of the United S Furthermore, that the corne 19, found, recovered, resi	19 82, established, in conformance with regulations states Department of the Interior, r points mentioned in lines 3, 4 tored, established or re-established ration for Land Surveyors or, by a
A. Description of original monu	ment and accessories a	and/or si	ubsequent restoration:	
West 1/16 corner on the	North Section	Line o	f Section 18. Not pr	eviously established.
West 1/16 corner on the	South Section 1	Lin⊜ o	f Section 18. Not pr	reviously established.
	nate between the South 1/4 cor	he Nor	th $1/4$ cor. and the N	ng corner: N.W. Sec. Cor. of Sec. 18. Sec. 18. (G.L.O. record
C. Description of monument for D.N.R. Monument. Beari		es establi: 15	shed to perpetuate locating the	
0	0.81	-	8" R. Maple, 527°W,	_
6" Tamarack, N57°W, 7	8.61		4" Cedar, N39°W, 5	53 <b>.7'</b>
4" Tamarack, S68°W, 4 4" Tamarack, S19°E, 5	0.4' 0.4'			72.0' 93.8'
SIGNED BY David E. Labb	B. Balkit	4	DATE 4-21-8	32
SURVEYOR'S MICHIGAN REC		<u> 558 </u>	<del></del>	(SEAL)