	L	AND CORNER RECORDATION CERTIFICA	TE B997871	
E	r corners in	iling Requirement of Act 74, Mich. P.A. 19	70 93 DEC 22 AM 9: 03	
F	MACOMB		÷ ,	
	(County)		CARMELLA SABAUGH REGISTIRE DE DEEDS	
	•	RLING TWP.	REGISTER OF DEEDS MACOMB COUNTY, MI	
1.		R <u>12E                                   </u>		
		R	LIBER 05161M221	
2.	Property Controlling S T		TIRER COTOTINEST	
3	in Section S T Miscellaneous S T	D		
O.	Property in Sec. S T	R	Register of Deeds Stamp & File Number	
4	Lot No, Recorded Plat			
	Private Claims		A B C D E F G H I J K L	
			2 - 6 - 5 - 4 - 3 - 2 - 1	
			3	
Ι, _	BRUCE ANTCLIFF , in a field survey	onNOVEMBER .22 19 93 ,	4 7 8 9 10 11	
do hereby certify that under requirements of P.A. 74. Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the				
		regulations and rules therefore as required in the discrete States Department of the Interior, Bureau of Land	7	
		or that the corner points mentioned in lines 3, 4 and 5	8 19 20 21 22 23 2	
		chigan Board of Land Surveyors or by a Decree of a numented, re-monumented, recovered, found as	9	
·	pressed below:		10 30 29 28 27 26 2	
NC	TE: Not more than 4 corners, all in the on this certificate.	same town and range, may be recorded	11	
	on this certificate.		12 31 32 33 34 35 3	
A.		cessories and/or subsequent restoration:		
	GLO-Post, NO WITS, REMAIN	LCRC (1977) L2886,P443-1" IRON N&T IN UTIL POLE, NE'LY, 41.09	LCRC (1988) L4795,P486-3/4" BAR CONC NAIL SE FACE UTIL POLE, NE, 52,14'	
	MCRC (1958)-REINFORCING ROD	N&T IN UTIL POLE, SE'LY, 41.92'	CONC NAIL SW FACE UTIL POLE, SE, 53.07	
	SPIKE IN 18" MAPLE, SW, 65.10' PK IN 14" ELM, SW, 42.30'	N&T IN UTIL POLE, SWLY, 38.21' TOP CENTER HYDRANT, NW'LY, 115.73'	CONC NAIL NE FACE UTIL POLE, SW, 65.60' CONC NAIL NE FACE UTIL POLE, NW, 52.00'	
	SPIKE DE POLE, NE, 40.40	LCRC (1979) L3106,P516-3/4" REBAR	LCRC (1989) L4774,P846-3/4" IRON/MON BOX	
	EDISON NOTES (1957)-3/8" REBAR	CENTER OF MH, N32W, 54.0' NAIL IN N FACE WOOD POLE, S60W, 38.10'	PK SW FACE UTIL POLE, SE, 52.89' PK&T NW FACE UTIL POLE, SW, 65.68'	
	EDISON NOTES (1960)-3/8" REBAR	PK SW FACE WOOD POLE, N60E, 40.30'	PK&T NE FACE UTIL POLE, NW, 52.15"	
	EDISON NOTES (1989)-MON BOX		PK&T SE FACE UT POLE, NE. 52-16	
В.	Description of corner evidence found and	d/or method applied in restoring or reestablishi	DENEL AND OFFICIAL THE CHAIRMAN	
	FOUND 5/8" REBAR/MON. BOX	FOUND 5/8" REBAR/MON. BOX THIS CORNER WAS RECENTLY REMONUMENTED BY MCRC. THE PREVIOUS CORNER AND		
		REMOVED DURING NEW ROAD CONSTRUC	TION. THE OOSE S	
		CUPIED CENTERLINE/CENTERLINE OF T	THE ROAD MUST SE	
	INTERSECTION.		ize5. Jig	
	VERIFIED 1989 EDISON DISTANCE		OZZ OR	
	AND TO K-4 (R=2593.71, M=2593.62)		Man	
			田でひる。	
			后说 <b>名</b> ▼ 1 3 1 3 1	
			7 H 3 K	
_			The position of the contract of the position of the contract o	
C.	Description of monument for corner and	accessories established to perpetuate locating	625	
	SET MACOMB COUNTY REMONUM! WITNESSES	ENTATION MARKER AND CAP #25826 IN EXIST	T. MON. BOX.	
	TOP CENTER FIRE HYDRANT	, N29W, 134.27	新 <b>伊</b> 罗里(1)	
	SET N&T NE FACE PP, N56W,			
	SET N&T SE FACE PP, S61W, SET N&T NW FACE PP, N60E,		1 X E 2 A 2 E 1 / 1 1	
		•	* SURVEYOR *	
	The selected location is accented by	me and is generally accepted by Professional S	Surveyors as No.	
	the best available evidence of the posi-			
		•	DIAND	
	Burn DADO	12 0	O S	
Sigi	ned by Duce Culcliff	Date 12-9-	<u> </u>	
Sur	veyor's Michigan License No. 2582	6	SPROVED BY MICHIGAN STATE ROARD DE FAND SHRVEYORS JAN. 28. 1	