SURVEY & REMONUMENTATION

APR 28 1995

For corners in

COMMISSION

LAND CORNER RECORDATION CERTIF

Washington

Filing Requirement of Act 74, Mich. P.A. 1970

C105002

	Macomb (County)	Located in: Township	Corner Code ##	LIBER 06415PG47	n
1.	Public Land Survey	T R	F-9	94 AUG -5 PM 1: 42 CARMELI A SABAUGH REGISTER OF DEEDS MACOMB COUNTY, MI	J
	Property Controlling in Section Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number	
4 . 5 .		tecorded Plat		2 6 5 4 3 2	L -1
do in I cur Mai abo Cou exp	hereby certify that under req ines 1 and 2 above were in rent manual of survey instru- nagement or by a decree of a love were in conformance with urt of Law; established, re- ressed below:	in a field survey on June juirements of P.A. 74, Michigan P.A. of 1970 in conformance with regulations and rules actions of the United States Department of a Court of Law and/or that the corner points the trules of the Michigan Board of Land e-established, monumented, re-monum	O, the corner points mentioned is therefore as required in the of the Interior, Bureau of Land is mentioned in lines 3, 4 and 5. Surveyors or by a Decree of a tented, recovered, found as	4 7 8 9 10 11 5 6 18 17 16 15 14 7 8 9 10 20 21 22 23 9 10 30 29 28 27 26	-13 -13 -24 -21
NOTE: Not more than 4 corners, all in the same town and range, may be on this certificate.				11 12 31 32 33 34 35	-36 -4
181 1. 2. 3. 4. 5. 6. 7. 8. 9.	7-GLO Wampler, D.S.; Set) 1975-Avey, P.S. #15396) 1976-Avey, P.S. #15396) 1983-Kobs, P.S. #14097) 1972-Avey, P.S. #15396) 1974-Avey, P.S. #15396) 1976-Avey, P.S. #15396) 1979-Avey, P.S. #15396) 1986-Kobs, P.S. #14097) 1986-Kobs, P.S. #14097 Description of corner ex	nonument and accessories and/or substitute of the post; 9"? S37*W 8 Links; 10" White for LCRC L.2560, Pg.308 - Fnd 1/2" Iron for LCRC L.2718, Pg.730 - Same with as for LCRC L.3488, Pg.551 - Fnd 1/2" Iron for Survey L.2314, Pg.243 - Same with for Survey L.2560, Pg.317 - Same with for Survey L.2718, Pg.737 - Same with for Survey L.2718, Pg.737 - Same with for Survey L.3756, Pg.649 - Same with for Survey L.3756, Pg.504 - Same with for Survey L.4077, Pg.584 - Same with for Survey L.4078 -	e Oak N23*E 36 Links on Pipe 1975 LCRC on Bar in a Monument Box as 1975 LCRC as 1983 LCRC as 1983 LCRC d in restoring or reestablishin		
199	94 Kennedy Surveying, Inc which has a bituminous	c Kennedy, P.S. #17623 - Fnd 1/2" s surface, and 96.0' West to driveway	Iron in a Monument Box, 4' 1 y to house #6821.	North of the centerline of 28 Mile Road	i,
	Witnesses from LCRC #1	1 and 3 were used to recover and ver	ify the location of the found	nd 1/2" Iron Rod in a Monument Box.	
	FIELD MEASUREMENT BETTE F-9 to E-9 2717.68 Fee F-9 to G-9 2688.87 Fee	et	ACCEPTED BY THE MACOMB GROUP AS THE OFFICIAL CO PUBLIC ACT 348 OF 1990 ON 7-12-94 WILLIAM E. SODERBERG	DAT A MEETING HELD	

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- F-9 I replaced the found 1/2" Iron Rod in a Monument Box with 3/4" x 24" Iron Rod w/2" diameter aluminum cap stamped "Macomb County Monument MI Act 345 #17623" in a existing Monument Box. THE OF MICH

Date

Due South 31.07' Set PK & Remon. Washer West face Power Pole

N40°W 38.65' Set PK & Remon. Washer NE face 12" Elm S60°W 77.85' Set PK & Remon. Washer SE face 10" Willow

N60°W 111.37' Set PK & Remon. Washer South face clump 10" Elm

The selected location is accepted by me and is generally accepted by Professional Surveyors as the best postion of the original corner.

Signed by 17623 Surveyor's Michigan License No.

1994 POFESSIONAL July 21,

WHITE OF MICHE