## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	rining Requirement of Act 74, Mich.	P.A. 197	U						
Macomb	Washington Twp Located In: Corner Code #		e108	. General Si Pi	<b>5</b> U	HVE	Y & NTA	TIO!	N
(County)	IN -10D 7 1		2	EW	OM	JME	[N 1 ]~	. 8 1607	1 %
Public Land Survey	T_4N R12E		FEB 2 7 1997						
	TR TR				CO	MMI	SSIC	M	
Property Controlling     in Section	S TR				The same				
3. Miscellaneous	STR								
Property in Sec.	<u> </u>		Re	egiste	r of D	eeds S	tamp 8	File I	Number
4. Lot No, Reco	orded Plat			B C	D.	E F	C 11	T 7	~ 1 1
5. Private Claims			1	֓֞֞֞֞֞֞֓֓֓֓֞֟֓֓֓֓֓֓֓֡֓֡֓֡֓֡֓	Ţ	E F	G H	Ţ	K L !
			3			1-1-			
, Huston K. Kennedy	, in a field survey on $\underline{8/1}$ , 19 $\underline{96}$ do hereby state tha	at under	4	-	— ķ—	   9	10-	  !}	1,2-
requirements of P.A. 74, Michig conformance with regulations and	an P.A. of 1970, the corner points mentioned in lines 1 and 2 above drules therefore as required in the current manual of survey instruction	were in ns of the	5	+	-			++	
	Interior, Bureau of Land Management or by a decree of a Court of Law d in lines 3, 4 and 5 above were in conformance with the rules of the M		6	18-	1 7	16—	15-	1/4	13
Board of Land Surveyors or by recovered, found as expressed by	y a Decree of a Court of Law; established, re-established, monur	mented,	7				$+ \pm$	+	
•			9 —	19	20 _	21   	1-22-	<del>23</del>	24
NOTE: Not more than 2 cor on this certificate.	mers, all in the same town and range, may be recorded		10	30	_29_	-28-	27-	26	25
			11		<u> </u>	<u> </u>	-		
			12	31—	_32	3,3	34_	3 <u>5</u> _	36
A. Description of original mo 1817-GLO Wampler, D.S.;	•	ACCEPTED.	<b>5</b> 3.4 <b>5</b> 1.4						
	P	SA YUUHAS	EPTED BY THE MACOMB COUNTY SURVEY PEER UP AS THE OFFICIAL CORNER UNDER MICHIGAN LIC ACT 345 OF 1990 AT A MEETING HELD						
	<del>-</del>	<u> </u>	fle	de	3	130	Teck	1	<u>-</u>
		VVII.L	IAGVI E.	30051	KBEKG	, P.S., C	HAIRMA	N	-
B. Description of corner evi	idence found and/or method applied in restoring or reestablish	hing corne	er: (	over)	)				
FIELD MEASUREMENTS 1	BETWEEN								
	2748.03 Ft. (GPS-MEA) 2516.40 Ft. (GPS-MEA)								
	C0458175 LIBER:07298 PAGE:200 10: CARMELLA SABAUGH-MACOMB COUNTY, N	:47A @ MI REG	11/0 S/DE	2/1 EDS	997 :				
C. Description of monument	t for corner and accessories established to perpetuate locating	g the posit	tion of						
\$66 W 95.58' Set PK 8 \$58'E 71.67' Set PK 8 N75'W 138.86' Set PK	ron Rod w/2" diameter aluminum cap stamped "Macomb Coun & Rémon Washer North face Power Pole & Remon Washer NE face Power Pole & Remon Washer NE face Power Pole & Remon Washer NW face Power Pole	nty Monume	ent MI	Act :	345" #	17623	in a ne constant of the consta	MICH	nument Bo
The selected location is position of the original	accepted by me and is generally accepted by Professio corner.	onal Surve	eyors	as th	ie bes	avaj.	KENN HOLES SURVI	EYOR EYOR	ge jost til
Signed by	Date	eDec	embe	er 10	0, 1	9963	ROFESS	600 -000 1011 KL	
Surveyor's Michigan License	No. 17623 V								

79

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995 1996 Kennedy Surveying, Inc. - Kennedy, PS #17623 - There has been some controversy about the location of this corner.

Researching the Macomb County Records for Land Corner Recordation Certificates (LCRC) and Certificates of Survey shows nothing has been recorded for this corner. I did not receive any information from the letters that were mailed to other sources.

Extensive research was done with the descriptions of the adjacent parcels, but they did not provide any additional information regarding the position of this corner.

## HOW THE CORNER WAS RECOVERED

The Macomb County Atlas that was published in 1875 and 1916 for Bruce and Washington Townships, shows a very large deflection at the South 1/4 corner of Section 36, Bruce Township and the North 1/4 corner of Section 1, Washington Township. The Macomb County Planning Commission 1966 aerial photography depicts a line of occupation extending South of 32 Mile Road for about one half (1/2) of a mile. This line of occupation represents the West line of the Romeo Golf Course that was use to recover this corner. I held the above mentioned fence-tree line and projected it North to the intersection of the existing centerline of 32 Mile Road to recover this corner. The South 1/4 corner of Section 36, T5N, R12E, Bruce Township (L-13) is being held as a common corner.

## HOW THE CORNER WAS RECOVERED

I held the distance between K-12 to K-13 as shown on the M.DOT M-53 Vicinity Map (Sta. 1250 + 00 to POE) recovering the corner 2636.38 feet following along a existing chain link fence and the remaining part of the fence post, which has been broken off at ground surface. The distance between J-13 to K-13 2657.26 feet measured and M.DOT 2657.15 feet. The corner is 5 feet South of the con-struction joint on 32 Mile Road.

C0458175 LIBER:07298 PAGE:201 10:47A 01/02/1997 CARMELLA SABAUGH-MACOMB COUNTY, MI REG/DEEDS

SURVEY & REMONUMENTATION

FEB 2 7 1997

COMMISSION