SURVEY & REMONUMENTATION

APR 2 9 1996

COMMISSION CO212008 LIBER:06663 PAGE:865 12:21P 06/06/1995 CARMELLA SABAUGH-MACOMB COUNTY, MI REG/DEEDS

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Macomb	Located In: Ray Twp.	Corner Code #		
(County)	Located in Ray 1wp.	Corrier Code #	1	
A Did Solomal Comme	т <u>4N</u> R 13E	A-12		
Public Land Survey	T R	R-12		
	T R			
2. Property Controlling	T R ST R			
in Section	S T R			
3. Miscellaneous	ST R		Register of I	Deeds Stamp & File Number
Property in Section	S T R		negister of t	Deeds Statiff & File Nutriber
	, Recorded Plat		——— А В	CDEFGHIJKL
5. Private Claims	<u> </u>		2 6	5 4 3 3 - 2 1 -
			3	
			4	
	y, in a field survey on <u>April 28</u> equirements of P.A. 74, Michigan P.A. of			
in lines 1 and 2 above were in	n conformance with regulations and rules	therefore as required in the	current	17 16 15 14 13 -
	ons of the United States Department of a Court of Law and/or that the corner			20 21 22 23 24 24
	ce with the rules of the Michigan Board stablished, re-established, monumented, i			
as expressed below:	· · · · · · · · · · · · · · · · · · ·		10 30	
NOTE: Not more than 4 of on this certificate.	corners, all in the same town and rang	ge, may be recorded	11	32 33 34 35 36
on this continuate.	'		13	
A. Description of origina 1817-GLO Preston, D.S.;	al monument and accessories and/o	r subsequent restorati	on:	
1.) 1973-Avey, PS #15396	i; LCRC L.2426, Pg.345 - Fnd 1" Pip	ę.		AND ANIMEN OURSEV DEED
2.) 1973-Avey, PS #15396	5; Survey L.2393, Pg.192 - Fnd 1 P	-	COMID AC THE REFICI	COMB COUNTY SURVEY PEER IAL CORNER UNDER MICHIGAN
			PUBLIC ACT 345 OF	1990 At A MEETING HELD
			Willen	C Society
		•	WILLIAM E. SOD	ERBERG, P.S., CHAIRMAN
R Description of corner	r evidence found and/or method app	olied in restoring or ree	establishing comer:	
1995 Kennedy Surveying.	Inc Kennedy, PS #17623 - Fnd 1"	Iron Pipe 4 ⁿ above gro	und with a tree-fenc	e row extending to the East, and
a tree-fence row ex	xtending to the North & South. The	East 1/4 corner of Se	ction 36, T4N, R12E,	, Washington Township, (M-12)
is located 38.82 fe	•			
Witnesses from LCRO	C #1 were used to recover and verif	y the location of the	found 1" Iron Pipe.	
FIELD MEASUREMENTS	BETWEEN			
A-12 to A-11 2688.	14 Ft.			
A-12 to A-13 2673.7				
A-12 to M-12 (Wash)	ington Twp.) 38.82 Ft. to the North	l .		
			1	
A-12 I replaced the four	ment for corner and accessories est nd 1" Iron Pipe with a 3/4" x 24" I	abusned to perpetuate ron Rod w/2" diameter	aluminum cap stamped	n or the corner: d "Macomb County Monument MI Act
345 #17623"	et PK & Remon. Washer West face 12			
N17°W 17.10' Set P	K & Remon. Washer SW face 10" Ash	Non		
N81°W 8.45' Set PK	& Remon. Washer NE face 11" Hickor			
North 38.82' East	K & Remon. Washer NW face 13" Bassw 1/4 corner of Section 36, T4N, R12N	7, Washington Township	(N-12)	Mounthing
	•			beside of Michigan the
The selected location is position of the original	s accepted by me and is generally l corner.	accepted by rrolession	iat outleante as mie	S PHISTON & E
			-	是 KENNEDY
West	<i>S</i> / ,		;	PROFESSIONAL SURVEYOR
Signed by	7—	Date	May 30, 19	9 6 17623
Surveyor's Michigan Lice	nse No. 17623	FORM	i approved by Michigan State E	ESSIUMEVISED-RAV 14, 1975
				COSTO WEVER SED JAN., 1983