LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.	A. 1970
Manage.	01.77
Located In: Corner Code # (County) Bruce Township	SURVEY & REMONUMENTATION
1. Public Land Survey	APR 0 7 1998
2. Property Controlling S T R in Section S T R 3. Miscellaneous S T R Property in Sec. S T R	SECTION Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	ABCDEFGHIJKL
5. Private Claims	2 6 5 4 3 2 1 1
I Huston K. Kennedy , in a field survey on 5/27 , 19 97 do hereby state that a requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above we conformance with regulations and rules therefore as required in the current manual of survey instructions. United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law at that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan decree of Land Surveyors or by a Decree of a Court of Law; established, re-established, monume recovered, found as expressed below:	ere in of the 5
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	9 -
	10 - 30 - 29 - 28 - 27 - 26 - 25 - 11
A. Description of original monument and accessories and/or subsequent restoration: 1817-GLO Wampler, D.S.; Set Post 18" Black Oak N34 8 91 Links; 18" Black Oak S21 1.) 1955 - "SUPERVISOR'S PLAT OF MOUNTAIN VIEW ORCHARD FARMS", L.44, Pgs. 19 & 2	20
B. Description of corner evidence found and/or method applied in restoring or reestablishin 1997 Kennedy Surveying, Inc Kennedy, PS #17623 - The corner as recovered is 2. Road extending to the East & West, which has a bituminous surface. There is corner is common with the North 1/4 corner of Section 3, T4N, R12E, Bruce T	40 feet North of the existing centerline of 32 Hi no line of occupation extending to the North. Th
See back side of LCRC for Field Measurements GROUP AS T FUBLIC ACT ON S	THE MACOMB COUNTY SURVEY PEER HE OFFICIAL CORNER UNDER MICHIGAN T 345 OF 1990 AT A MEETING HELD T 347 OF THE MACOMB COUNTY SURVEY PEER HE OFFICIAL COUNTY S
C. Description of monument for corner and accessories established to perpetuate locating the H-13 I set a 3/4" x 24" Iron Rod w/2" diameter aluminum cap stamped "Macomb Count N27°E 35.85' Set PK & Remon Washer NW face 27" Maple N67°W 82.14' Set PK & Remon Washer South face 25" Maple S71°W 211.31' Set PK & Remon Washer SW face 24" Oak S11°W 127.66' Set PK & Remon Washer East face 12" Elm The selected location is accepted by me and is generally accepted by Professional position of the original corner.	y Monument HI Act 345 4 623 in a new Monument B HUSTON KENNEDY PROFESSIONAL SURVEYOR 17623
Signed by Date	E-15- 97
ourregor o innotinguir mourito (10	

HOW THE CORNER WAS RECOVERED

The point of beginning of "SUPERVISOR'S PLAT OF MOUNTAIN VIEW ORCHARD FARMS", Liber 33, Pages 19 & 20 of Macomb County Records, is the Southwest corner of Section 34 (G-13) and extending 3603 feet to the East long the South line of Bruce Township, but does not indicate the position of the South 1/4 corner of Section 34 (H-13). The North 1/4 corner of Section 3, T4N, R12E, Washington Township (H-1) does validate the monumentation along the North side of 32 Mile Road. The Macomb County Peer Group accepted the position of this corner as common corner with the North 1/4 corner of Section 3, T4N, R12E, Washington Township (H-1).

FIELD MEASUREMENTS BETWEEN

H-13 to G-13

GLO = 40 chains or 2640.00 Ft. GPS-MEA = 2678.23 Ft. or GROUND CAL. 2678.47 Ft.

H-13 to H-1

No GLO Common Corner

H-13 to I-13

GLO = 40 chains or 2640.00 Ft. GPS-MEA = 2625.59 Ft. or GROUND CAL. = 2525.83 Ft.

> C0568793 LIBER:07613 PAGE:809 10:28A 09/02/1997 CARMELLA SABAUGH-MACOMB COUNTY, MI REG/DEEDS