For corners in  Macomb	LAND CORNER RECORDATION Filing Requirement of Act 74,  Located In: Bruce TwpCorner Code #		SURVEY & REMONUMENTATION
(County)	1 00mg 000e #		FEB 2 7 1997
Public Land Survey     Property Controlling in Section     Miscellaneous	T-5N R 12E		COMMISSION
Property in Sec.	S IK		Register of Deeds Stamp & File Number
4. Lot No, Reco	rded Plat	1 A	B C D E F G H I J K L M
United States Department of the that the corner points mentioned	, in a field survey on 4/12, 1996 do hereby an P.A. of 1970, the corner points mentioned in lines 1 and 3 trules therefore as required in the current manual of survey in Interior, Bureau of Land Management or by a decree of a Court III lines 3, 4 and 5 above were in conformance with the rules of a Decree of a Court of Law; established, re-established elow:	tructions of the 5 class of the Michigan	-6 - 5 - 4 - 3 - 2 - 1
	ners, all in the same town and range, may be recorded	9	$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$
1817-GLO Wampler, D.S.; § 1.) 1980-Miller, PS #1358	nument and accessories and/or subsequent restoration of the Post 24" White Oak N21°E 11 Links; 24" Elm Start Care L.3288, Pg.637 - Fnd Disc on Copperclade LCRC L.5347, Pg.565 - Fnd Disc on Copper Rod	3°W 7 Links Rod  ACCEPTED F GROUP AS T PUBLIC AC ON	BY THE MACOMB COUNTY SURVEY PEER THE OFFICIAL CORNER UNDER MICHIGAN T 345 OF 1990 AT A MEETING HELD TO SURVEY THE MACOMB COUNTY SURVEY PEER THE MACOMB COUNTY SURVEY SURVEY SURVEY SURVEY
1996 Kennedy Surveying, In Road extending to th was recovered 14.06		stablishing corner: on Rod 0.5 feet Sou orth 1/4 corner of	th of the existing centerline of 32 Mile Section 2, T4N, R12E, Washington Twp.,
FIELD MEASUREMENTS B	#1 & 2 were used to recover and verify the locat	ion of the found (c	opper Clad 1/2" Iron Rod.
J-13 to I-13 GLO = 4 J-13 to J-1 NO GLO,	O chains or 2640.00 Ft., 2262.16 Ft. (GPS-MEA) 14.06 Ft., (MEA) and 13.96 Ft. L.3288, Pg.637 O chains or 2640.00 Ft., 2657.00 Ft. (GPS-MEA)		
	for corner and accessories established to perpetuate lo	cating the position o	f the corner:
S12°E 27.41' Set PK 846°W 48.94' Set PK 8574°E 91.94' Top Bolin55°E 55.74' Set PK 8	Copper Clad 1/2" Iron Rod with a 3/4" x 24" Iron #17623 in a new Monument Box  Remon Washer West face Power Pole  Remon Washer NW face 14" Maple ton Fire Hydrant Remon Washer SW face 16" Maple 1 1/4 corner Section 2, T4N, R12E, Washington Tw		aluminum cap stamped "Macomb County  OF MICH HUSTON KENNEDY as the best avenesses aven
position of the driginal (	accepted by me and is generally accepted by Prof	12-12	
Signed by Surveyor's Michigan License N	lo. 17623	Date	TO FESSIONAL CONTROL OF THE PROPERTY OF THE PR

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14,1975
REVISED JAN., 1983
REVISED OCT., 1995

622