DEG 2 9 1996

COMMISSION

REGISTER'S OFFICE

MANISTEE COUNTY 97-385 at 3:05 pm 0CT 17 1997

REGISTER OF DEEDS

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Corner Code #

Southeast Sec.

Cor. Sec. 13

M-07

Located In:

T

T 21N R 17W

For corners in

(County)

1. Public Land Survey

<u>Manistee</u>

2. Property Controlling in Section S T R 3. Miscellaneous S T R Property in Sec. S T R	IbW AOT	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat		
5. Private Claims		A B C D E F G H I J K L M  2
· · · · · · · · · · · · · · · · · · ·		3 9 10 11 2
i, Anthony M. Slawinski, in a field survey under requirements of P.A. 74, Michigan P.A. of 1970 above were in conformance with regulations and rules survey instructions of the United States Department of by a decree of a Court of Law and for that the corne were in conformance with the rules of the Michigan Court of Law; established, re-established, monumented	the corner points mentioned in lines 1 and 2 therefore as required in the current manual of the Interior, Bureau of Land Management or points mentioned in lines 3, 4 and 5 above Board of Land Surveyors or by a Decree of a	7
NOTE: Not more than 2 corners, all in the sam on this certificate.	e town and range, may be recorded	12 31 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration: M-7 Southeast Section Corner of Section 13, T21N., R17W.		
Set by John Brink in 1837  1. B. Oak 12" S 34° W 28 links (Gon  2. W. Pine 11" N 41° W 37 links (Gon		
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner; M-7 Southeast Section Corner of Section 13, T21N., R17W.		
Found Iron by Cole (1972) 3. S 45° W 37.72′ Power Pole (Gon 4. S 45° E 31.18′ Telephone Pole (Gon	Also referenced: e) GLO Original Field not	tes by Brink (1837), Book 1, Page 415 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5
Vailliencourt LCRC No. 72-2 (1972) 5. S 50° E 43.86' Top of Fire Hydrant (Gon	Mears engineering - S	Survey (1990), Liber 2, Page 188
6. S 40° W 37.80′ Power Pole (Gon	e) Slawinski- Fraverse si e) Voillioncourt LCRC /7	neet, field notes & survey (1982)
Found Iron by Slawinski 7. S 65° W 37.72′ 6″ Ash (Gon	e) Zwar- Survey (1996)	heet, field notes & survey (1982) 2-2) 1972 2-2) 1972 2-2) 1972 3-3
On July 28, 1997 I (Anthony Slawinski) & Abone found a 1 Iron Pipe.	marche Oak Hill Plat (Dec. 29	, 1890), Vol. 2 of Plats, Page 114 % Sheet & Survey (1972)
Todald a 1 abil tape.	Cole - Survey Travers	e Sheet & Survey, (1972)
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: M-7 Southeast Section Corner of Section 13, T21N., R17W.		
mentioned 1" iron pipe as a careful and faithful re-establishment of the position of the original corner and witnessed by:		
8. N 39° E 94.10′ Southwest Corner of Buildi 9. N 72° W 91.45′ Power Pole (Spike in the No 10. S 52° W 48.15′ Power Pole (Spike in the No 11. S 69° E 58.60′ Power Pole (Spike in the So Corner was set in the intersection of the center in	ortheast side) Northwest side) outhwest side) lines of 28th Street and Nelson Street.	итноиу Су
Signed by Anthony M. Slaunshi  Surveyor's Michigan License No. 13597  Surveyor's Michigan License No. 13597  Surveyor's Michigan License No. 13597		
	FORM APPROVED BY MIDDIGA	/ 4 /