

MAY 1 6 1997

Coldensing

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Lot cours	512 III			
MANISTEE	(County)	Located In:	Corner Code ##	REGISTER'S OFFICE MANISTEE COUNTY
1. Publi	c Land Survey	T R	Indian Reserve	#96-304 AT 10:15 A.M. JUL 17 1996
2. Prope	erty Controlling	T R T 22N R 15W S T R R	INDIAN RESERVE A-RI OTHER CODE #2	REGISTER OF DEEDS
	ction elianeous erty in Sec.	S T R S T R S T R		Register of Deeds Stamp & File Number
4. Lot N	lo , Re	corded Plat		— ABCDEFGHIJKLN
•		·		3 3 4 7 8 9 10 11 12
do hereby in lines 1 current ma Managema above wer Courl of expressed	certify that under requi and 2 above were in c anual of survey instruc ent or by a decree of a C e in conformance with Law; established, re- I below:	irements of P.A. 74, Michigan P.A. conformance with regulations an tions of the United States Depar Court of Law and/or that the corne the rules of the Michigan Board cestablished, monumented, re-r	of 1970, the corner points mention of rules therefore as required in the therefore as the ther	the the defined the state of th
	Not more than 4 cor on this certificate.	ners, all in the same town ar	id range, may be recorded	12 31 32 33 34 35 36
A Desc	ription of original me	onument and accessories and	t/or subsequent restoration:	13
	,	orner , T22N, R16W, on Eas	100)] Jenema same as Gerschbacher
`				phon PIC #19000
	John Brink , 183 Cross Indian Res		1975, L. Gerschbad SET Empl 3/4" x 18" 1	Iron Bar, reise d w/ 1½" Iron Pipe
	@ 40.57 chains	erve tine	#3 Power Pole s39 #4 Cherry SO4°W	50W 140.62 Jakub
B. Desc M-08 I	#1 W. Pine Stum #2 W. Pine Stum ription of corner evid	en- Book "B", pg. 96 p 20" S52½°W 201ks.(13.2 p 18" S 57°E 571ks.(37.6	pplied in restoring or reestab	58°W 98.20' #8 Red pine 8" N58°W 98.46' 6 #17834 East 1/4 Cor. South 38.28'
	On May 6, 1	996, I found 5/8" Iron Ro	od w/ RLS Cap # 18990, be	elow the Rod · I also found 11/2" Iron Pipe. idence to disputed this location for the
	Condition of recomplete the co	orded witnesses are; d condition	#6 Found in poor condit #7 Same as 5 #8 Same as 6 M - Comercing to the	ratified by the Marristee County Peer Ground Plan adopted pursuant to P.A. 345 of 199 adopted pursuant to P.A. 345 of 199 adopted pursuant to P.A. 345 of 199 adopted pursuant for Feer Review. Soft Peer Review. Indicate County Monument, set 1 foot peestablishment of the position of the
C. Desci	riotion of monument	for corner and accessories a	degraphists of the stability of the stab	of Peer Review. Training
4-08 I	Indian Reserve C	orner, T22N, R16W, on the	Township Line	the position of the comer.
	I repaced bo below the road s original corner.	th existing Irons, in the urface, and is accepted as	exact location with a Star a careful and faithful re	ndard Manistee County Monument, set 1 foot pestablishment of the position of the
	(OBT #5) Wild Ch Cut-off Red Pin Red Pin	erry 20" S 75° E 57.74 Power pole N 60° E 3 e 10" S 38° W 110.88° e 11" N 65° W 101.85°	' (60d spike in NE side of 4.62'(60d spike in NW side (60d spike in NW side of t (60d spike in NE side of t	SAMMY S. BARNETT PROFESSIONAL SURVEYOR No.
			Date 6-	26-96 16923
Surveyor ⁱ s	s Michigan License I	vo. <u>16923</u>		ORM APPROVED BY MICHIGAN STATE BOME OF TAND URLEASTS, JAN. 20, 1971