

MAY 1 6 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in MANISTEE (County)	Located In:	Corner Code#	REGISTER'S OFFICE MANISTEE COUNTY #06-364 AT 10:15 A.m. AUG 2 3 1996
1. Public Land Survey	T_24N_R_15W TR TR TR	<u>C-6</u>	Penny a Roma REGISTER OF DEEDS
2. Property Controlling S	T R R R R R R R R R R R R R R R R R R R		Register of Deeds Stamp & File Number
4. Lot No Records 5. Private Claims	ed Plat		
do hereby certify that under requirent in lines 1 and 2 above were in conficurrent manual of survey instructions Management or by a decree of a Courabove were in conformance with the Court of Law; established, re-est expressed below: NOTE: Not more than 4 corne on this certificate. A. Description of original mon C-6 1/4 Cor., 17 & 18-24-1839 John Brink (1) 8" Beech 8 35 W 1 (2) 8" Beech N 65 W 1	nents of P.A. 74, Michigan P.A. formance with regulations are of the United States Depart of Law and/or that the cornules of the Michigan Board tablished, monumented, resers, all in the same town ument and accessories at 15.	A. of 1970, the corner points mentioned rules therefore as required in the ment of the Interior, Bureau of Lancer points mentioned in lines 3, 4 and 5 of Land Surveyors or by a Decree of a monumented, recovered, found as	3 4 7 9 10 11 12
B. Description of corner evider C-6 1/4 Cor., 17 & 18-24-1 Aug., 1971, Slawinski (3) 30" Beech (tag) S (4) 12" Maple (tag) N (5) 8" Beech (tag) No Jul., 1996, K. Ross Ed	5 Fd. 1" x 1" Iron St. B 24.25' W 17.26' rth 9.87'		shing corner:
		according to the contilly bigu	ratified by the Manistee County Peer Group adopted pursuant to P.A. 345 of 1990, Survey and Remonument Act, MCL 54.261 ALIC 6 1996 Authorized Remonument Act, MCL 54.261
Fd. Witness \$4 (now 19))) & 5 (top broken of: Square Iron with Star lence of the original 27.03' (Spike) 44.50' (Spike)	Mand Mantakan managara	