SURVEY & REMONUMENTATION

MAR 1 6 1998

	CAND CON	inch recombiting centricit	,,,,,,					
SECTION	Filing Requi	Filing Requirement of Λct 74, Mich. P.Λ.		FII	ED			1
For corners in	Louistantinu	Course Code #	AT 10:	3 <i>7</i> orc	OCK _	A	N	1
MASCN trendyl	Located In:	Corner Code #		NOV I		,		
1 - Public Land Survey	T 17N R 17M . T 17N R 16W	M·3						
2.5.4.6.4.11.4	T R			ARY GOLU Mason Register	COUNT	Y		_
2 Property Controlling S in Section S	T R	·	\					
3. Miscellaneous	T R R R		Register	of Deeds	Stamp	& File	Numb	er
Froperty in Sec. S	TR	.						
4 Lot No. , Recor	ded Plat			n	. ,	c u		
5. Private Claims			1,1	1 B C b	1	1 D	, , , i	. 1 64
			2	6 5	1	3	2	1 1
			3(3)					. 6
I. THEODORE H. WEINERT , in a field survey on SEPTEMBER 15, 1997 ,			4	7 8	Ŷ	10	11	12
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned			5					
In times 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land			۸	1N 17	16	15	1.4	[11]
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5			7					
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Could of Law, established, to established, monumented, to monumented, recovered, found as			л	19 20	21	22	23	24
eviseaned follow	еминаен, пининенен, те	monuntument, recoverent nouth as	?		İ			
			10	3n 29	28	27	26	25
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this cartificate					1			

Corner Common to Section 1, and Section 12, T. 17N., R. 17W, and Section 6 and 7, T. 17N., R. 16W., Township lines and Original Corner established by Mullet and Brookfield, July, 1837. Stated Beech, 12" for corner Sections 1 and 12, no witnesses given, C. E. Milchell, 1908, MCRC records, fied this comer, does not state what he found, no witnesses given, distance north to corner M. 1, 5178.36', C. E. Mitchell, 1911, MCRC records, tied this corner, does not state what he found, no witnesses given. distance south to comer M-4, 2633', distance south to comer M-5, 5266'. Kenneth B. Stephens, RLS, 1964, drawing Humber B. 62, stated "reestablished from witnesses, No witnesses given, distance north to comer M 2, 2641.30", County Road Commission Records, 1966, state iron, set monument box, witnesses given, (1) pipe, \$ 45° W, 46.67', (2) pipe, N 45° W, 46.67',

(3) Maple, 10", N 23" W, 142', (4) Pipe, East, 33.00', Kenneth L. Ross, RLS, 1992, drawing number 92061S, states monument box, no witnesses given, distance south to corner M-4, 2633.09', distance south to corner M-5, 5269-43'. No other witnesses found during research of this comer.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Description of original monument and accessories and/or subsequent restoration:

I found a 3/" to 1" solid steel bar, (12" below the road surface), in a monument box. On the center line of Scottville Road and the center-line of Kinney Road to the West, Witnesses (1) and (2) have been removed or destroyed. Witness (3) remains standing and is in excellent condition.

Description of monument for corner and accessories established to perpetuate locating the position of the corner

Heff the XC to 1" solid steet bar in place in the described monument box on the center-line of Scottville Road and the center line of Kinney Road to the West, and accepted this as the best available evidence of the location of the original corner Witnesses checked or taken:

- (3) Existing Spike in 24" Maple, N 23° W, 142.15'
- (4) Set spike in Power Pole, S 75° W, 69.62'
- (5) Set spike in Power Pole, S 50° W, 47.05°
- (6) Existing spike in Service Pole (with two telephone boxes by il), S 15° F, 44.23'
- (7) Distance South to comer M-4, 2633.10' (verified 9/23/97) (8) Distance North to Comer M-2, 2641.65', (verified 9/23/97)

Surveyor's Michigan License No. 19846