## OCT 2 9 1998

## **MECOSTA COUNTY REMONUMENTATION PROGRAM**

CORNER APPROVED BY PEER GROUP ON AUGUST 8, 1997

## SECTION

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN COUNTY OF MECOSTA RECEIVED FOR RECORD

<b>(**</b>	ining troqui	1011011 01 1 101 1 - 4, 111011 1 1 1 1	RECEIVED FOR RECORD
For corners in MECOSTA	Located In:	Corner Code #	
(County)			198 AUG 19 A9:53
Public Land Survey	T_13N_R_10W_	H-11	Joanne Brown
	TR TR TR		REGISTIK OF DEEDS
2. Property Controlling	STR		
in Section  3. Miscellaneous  Property in Sec.	S T R S T R R S T R R R R R R R R R R R	Re	gister of Deeds Stamp & File Number
4 Lot No. , F	Recorded Plat		
5. Private Claims			ABCDEFGHIJKL
			2 6 5 4 3 2 1
I, JACK E. PIERSON	, in a field surv	ey onOCTOBER 10,_1997_,	4 7 8 9 10 11 12
I, JACK E. PIERSON , in a field survey on OCTOBER 10, 1997, 4 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the			
current manual of survey instructions of the United States Department of the Interior, Bureau of Land 6 18 15 15 15 14 Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5			
above were in conformance	with the rules of the Michigan Board	d of Land Surveyors or by a Decree of a re-monumented, recovered, found as	7 8 19 20 21 22 23 24
expressed below:	,, ,, , , , , , , , , , , , ,		9
			10 30 29 28 27 26 25
NOTE: Only one corner	r may be recorded on this cert	ificate.	12 31 32 33 34 35 36
A. Description of restoration:	original monument and a	ccessories and/or subsequent	12 31 32 33 34 35 36 13
	42 CHS. ENTER TAMARACK SW 40 CHS. LEAVE SWAMP 81 CHS. INTERSECT E. BOUNI WEST CORRECTED - 40.50 CH TAMARACK - 4 - S62°W - 11	DARY 5. – SET POST LKS	S 27 AND 34 -
	TAMARACK - 8 - N85°E - 48	LKS	
COUNTY SURVEYOR RECOR COUNTY SURVEYOR, ON	D BOOK NO. 1, PAGE 59 AT RE JUNE 6, 1899, CORNER NOTED	GISTER OF DEEDS OFFICE SHOW NO AS, "STAKE - 40.4 CHS. TO S.W.	TES BY L.W. JUNE, COR."
MDOT FREEWAY PLANS (1	19" YELLOW BIRCH - 11" WH.BIRCH - S20 11" WH.BIRCH - S45	°E ~ 45,56′	' REBAR
		ED BY WILLIAM TINGLEY, P.S. 30	0104
IN 1981 J. E. PIERSON FOUND AND USED THE 7/8" REBAR AS THE CORNER			
IN 1996 J. E. NO EVIDENCE OI	PIERSON FOUND SAME 7/8" RES F THE 2" ANGLE IRCN WAS FOUN	BAR IN BENT CONDITION AND REPL	ACED WITH %" PIPE
B Description of cor	ner evidence found and /or me	ethod applied in restoring or rees	tablishing corner
ON OCTOBER 10, 1 WITNESS(POWER PO	997, FOUND %" PIPE MENTIONE LE), OTHER MOOT WITNESSES	D ABOVE. CONFIRMED POSITION E HAVE BEEN DESTROYED IN THE PRO	Y MEANS OF ONE MDOT CESS OF DITCH EXCAVATION,
H-11 - QUARTER CORNER FOUND 34' PIPE AND ACC	COMMON TO SECTIONS 27 AND	34, T13N-R10W HFUL PERPETUATION OF THE POSIT MONUMENT OVER THE %" PIPE.	cocating the position of the corner:  PION OF THE ORIGINAL CORNER.  1. 265°, 163.96 FEET
P. POLE (MDOT TAG)		OF MICH. AZ	300°, 68.84 FEET
4" ELM P. POLE	on 20 Hours	AZ AZ	•
FENCE LINE NORTH - EA	ST 30 FEET	# JACK E. # PIERSON # LAND # SURVEYOR #	
	16	N. 19305	
Signed by	k & Juson		July 20, 1998
Surveyor's Michigan Lice	nse No. 19305	FORM APP	ROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1
( )			REVISED MAY 14, REVISED JAN, ADAPTED FOR WORD BROCKESING MARCH
$\circ$		APPRO	VED BY MECOSTA CO. PEBR GROUP

LIBER 100 PAGE 429

MARMAN TO FUG. 8 1908

IN ACCORDANCE WITH P.A, 345 of 1990