

## MAR 0 3 1999 MECOSTA COUNTY REMONUMENTATION PROGRAM CORNER APPROVED BY PEER GROUP ON AUGUST 14, 1998 FAIL OF MICHIGAN COUNTY OF MEDISTA FEDERIVED FOR RECORD

SECTION

	F1111	ng Requirement o	OT ACT 74, IMICH.	P.A. 1970	,						
For corners in  MECOSTA (County)	Located In:	Corner Code #						EC 28			
1. Public Land Survey	T 15N R ( T R T R		-11		REGISTER OF DEEDS						
<ol> <li>Property Controlling in Section</li> <li>Miscellaneous Property in Sec.</li> </ol>	STR			Re	giste	r of D	eeds S	tamp &	k File N	lumbe	Γ
4 Lot No, R	ecorded Plat				. /	. в (	C D	E F G	; } H [	JK	L
5. Private Claims				-	2		5	:	3	2	<del> ,</del>
I, JAMES G. KNAPP do hereby certify that unde	, in a r requirements of P.A. 74,	field survey on Michigan P.A. of 1970	MAY 13, 1	998, entioned in		7	8	9	10	11	1:
lines 1 and 2 above were current manual of survey in Management or by a decree	e in conformance with renstructions of the United e of a Court of Law and/or	egulations and rules States Department or that the corner points	therefore as required the Interior, Burea mentioned in lines	red in the u of Land 3,4 and 5	5	18	17	- î - 1ŏ	15	14	
above were in conformance with the rules of the N Court of Law; established, re-established, m expressed below:						19	20	- <b>2</b> ]	22	23	- 2
					9 10	30	29	28	27	26	- 2
NOTE: Only one corner	may be recorded on the	nis certificate.			11	SO.	29	20 ···	2/	20	
A. Description of origi	not monument and ag	acception and/or o	these transfer	ations	12 13	31	32	<b>3</b> 3	34	35	3
BROOK 15 LINKS COURSE IN 1896, LYMAN W. JUN SURVEY CORNERS IN T15; 'MAPLE 12" N66°W 11 'BEECH 18" S72°E 18 ROAD SURVEY NOTES AT 1	E, COUNTY SURVEYOR, N-R8W, AS RECORDED I = O.B.T. = O.B.T. MECOSTA COUNTY ROAD	MAPLE WAS APPOINTED BY N COUNTY SURVEYOR COMMISSION, BY E.	THE MARTINY TOWNS RECORD BOOK N	LINKS - NSHIP BOA O. 1, PAC	(7.2) ARD 1 GES 2	FEE1 O PER 90 AN	PETUAT D 291. S CORN	CORNI	ER NOT	ED AS,	
0°-10' R. 1/4 POST 28 38+83 35, AND WITNESS		CORNER AT STA. 0 S27°W 58.2° N46 1/2°E 52.9°		RNER AT S	TA.	52+44	, AND	A STRE	АМ АТ	STA.	
CORNER RECORDED AS PEI FOUND 3/8" ROD INSIDI		RAISED TO SURFACE N51°W 159.6 N72°E 88.4	: WITH 3/4" GALV 7' 4'					SEPT.	30, 1	975 ,A	5;
IN ACCORDANCE CHAIRMAN DAYE  APPROVED BY M IN ACCORDANCE	H. K. 345 of 1990  H. K. 345 of	T15N R8W", AND WI	TNESSED: 8" MAI 6" POS 14" W. 8" R.	PLE S T N PINE S PINE N	09°E 84°E 40°W 32°W	50. 88. 48. 63.	99' 40' 38' 10'				
CORNER IS 1.6 FEET OF WITH FENCE - SOUTH.	13 MILE ROAD (20' B	ITUMINOUS), AND I	N LINE WITH 95 <sup>TH</sup>	. AVENUE	(22)	GRAV	ET - J	NORTH)	, AND	IN LIN	E
COUND CALLED FOR 36" I	PINE STUMP BY E.E. S	OURS IN 1916, AZ.	208°, 58.2 FEET	r							
C. Description of moni	ument for corner and a	accessories establi	shed to perpetua	te locating	g the	positi	on of t	the cor	ner:		

Surveyor's Michigan License No.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-11, 1/4 CORNER COMMON TO SECTIONS 28 AND 33, T15N-R08W

FOUND 1" O.D. X 14" TRON PIPE, BURIED 15" BELOW GRAVEL ROAD SURFACE, AT 28" FOUND 1/2" IRON ROD INSIDE OF VITRIFIED CLAY TILE AND SURROUNDED WITH STONES, AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER.

REMOVED THE 1" O.D. X 14" IRON PIPE, AND PLACED A STANDARD MECOSTA REMONUMENTATION MONUMENT OVER THE 1/2" IRON ROD INSIDE OF VITRIFIED CLAY TILE AND SURROUNDED WITH STONES, INSIDE OF A HIGHWAY MONUMENT BOX, AND WITNESSED:

SET 60d SPIKE W/REMONUMENTATION TAG IN S.E. SIDE UTILITY POLE AZ. 58°, 171.98 FEET

FOUND SPIKE

IN WEST SIDE 12" MAPLE AZ. 170°, 50.83 FEET

FOUND SPIKE W/TAG NO. 30104

IN N.E. SIDE 14" WHITE PINE AZ. 215°, 48.14 FEET

FOUND SPIKE W/TAG NO. 30104

IN N.E. SIDE 10" RED PINE AZ. 326°, 63.38 FEET

Date OCTOBER 26, 1998 Signed by

wines 6 HAPP

LIBER 101 PACE