SURVEY & REMONUMENTATION

APPROVED LAND CORNER P.A. 345 OF 1990 MIDLAND COUNTY

OCT 0 3 1996

alialal MA

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act To Art To Filing Requirement of Act 74, Mich. P.A. 1970

4/2/76	9.U
	
	•
For corners in	
Midland	

Property in Sec.

Corner Code # Located in: (County) T 15N R 2E 1. Public Land Survey R R T R 2. Property Controlling R in Section R 3. Miscellaneous R

STATE OF MICHIGAN HIDLAND COUNTY REHONUMENTATION & FILED

22 AUG 96 8:06 A.M.

BEVERLY J THAYER REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4.	Lot No,	Recorded Plat	<u> </u>
5.	Private Claims		

I, RODNEY CLAYPOOL, in a field survey on JUNE 21, 19 95, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below:


NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

ABCDEFGHIJKLM 2 3 4 5 ìз ì 8 ÌΔ б 16 7 ŻΟ Ż4 8 19 9 Ż5 10 11 12

A. Description of original monument and accessories and/or subsequent restoration:

Corner common to four Townships T14 & 15N-R2E and T14 & 15N-R3E M-13

> Survey by Government (H. Parke), 1831, set post Survey by F. Gibbs, 1924 Survey by Hunter, 1962 H-W witness card, 1972 Survey by J. Jones, 1981 LCRC by C. McVean, 1994, (Bay Co. Remon Cor)



WITNESS NOTE: Witnesses from above surveys and LCRC's are available in dossier file; which was presented to peer review committee and is on file at the Register of Deeds Office.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-13 Corner common to four Townships T14 & 15N-R2E and T14 & 15N-R3E

Verified by witness card of 1972 (H-W Eng.)

Found iron and brass cap in mon box (Bay Co. Remon Cor.), per surveys by M. Hunter, J. Jones, and LCRC by C. McVean.

Corner was approved for remonumentation at a Peer Review Committee Meeting on 4/18/96.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-13 Corner common to jour Townships T14 & 15N-R2E and T14 & 15N-R3E

> Found iron and brass cap in mon box (Bay Co. Remon Cor.), per surveys by M. Hunter, J. Jones, and LCRC by C. McVean; and is accepted as the best available evidence of the position of the accepted corner.

S 45 Deg W, 42.07', nall and Bay Co. disc in power pole N 45 Deg W, 89.42', nail and Bay Co. disc in power pole N 40 Deg E, 79.80', nail and Bay Co. disc in power pole \$ 30 Deg E, 137.85',nail and Bay Co. disc in power pole

Signed by Modran O.

05-10-96 Date

Surveyor's Michigan License No. 2924

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971 Revised May 14, 1971 Revised Jan., 1983