MAR 2 1 1997

For corners in Muskegon

1. Public Land Survey

2 Property Controlling

Miscellaneous

Property in Sec.

in Section

5. Private Claims

expressed below:

LIBER 1952 PAGE 573

STAIL	€U }	 100%
COUNTY		
1: 1: 1: 1:		

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

PM 070 07 11 1: 07

ment of Act 74, Mich. F.A. 1970				
Corner Code ##	Cost 1286			
J-4	A1817			
	/			
	Register of Deeds Stamp & File Number			

I Stephen V. Vallier, P.S. , in a field survey on NOVEMBER 29 , 19 96 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

Located In:

_ T _

Т

s

. Recorded Plat

T 10N R 17W

R

R.

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- 2 6 5 4 3 2 10 12 12 15 16 15 14 13 7 8 19 20 21 22 23 24 9 10 30 29 28 27 26 25 11 12 31 32 33 34 35 36
- A. Description of original monument and accessories and/or subsequent restoration: CORNER NOT SET BY G.L.O.
 - 1945 CENTER OF SECTION SET BY M. BUCK AT INTERSECTION OF QUARTER LINES.
 - 1964 F.F. SMITH SURVEY ACCEPTED & USED CENTER OF SECTION ESTABLISHED BY M. BUCK
 - 1966 NORTHLAND PARK NO. 3 RECORDED IN LIBER 14 OF PLATS, PAGE 14. ESTABLISHED EAST 1/4 CORNER ALONG EAST/WEST 1/4 LINE AGREES WITH M. BUCK
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND ½" IRON PIPE 16½" LONG AT INTERSECTION OF FENCE LINES. ACCEPTED CORNER SET BY M. BUCK AND PERPETUATED BY HISTORICAL USAGE AND DOCUMENTATION.

NO WITNESSES OF RECORD BUT FOUND CORNER IS 0.50' NORTH AND 0.65' EAST OF COMPUTED CENTER OF SECTION.

POSITION OF SAID
RECORDED CORNER
REVIEWED & RATIFIED 8/13/9
BY MUSKEGON COUNTY
PEER GROUP IN ACCORDANCE
WITH P.A. 345, OF 1990

STEPHEN
VALLIER
Land
Surveyor
No.
28428

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

REPLACED 1/2" X 161/2" IRON PIPE WITH 21/2" X 30" CAST IRON MONUMENT WITH COUNTY SURVEY CAP.

SOUTH 85° WEST	 16" OAK	FOUND SPIKE IN SOUTH SIDE
NORTH 10° WEST	10" OAK	FOUND SPIKE IN EAST SIDE
SOUTH 10° WEST	10" MAPLE	FOUND SPIKE IN EAST SIDE
NORTH 82° EAST	10" OAK	FOUND SPIKE IN NORTH SIDE
NORTH 06° EAST	20" WHITE OAK	SET SPIKE IN EAST SIDE
SOUTH 22° EAST	8" MAPLE CLUSTER	SET SPIKE IN EAST SIDE
SOUTH 83° EAST	 STEEL FENCE POST	

Signed by Signed by Signed by

Surveyor's Michigan License No.

> FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 197: REVISED MAY 14, 197! REVISED JAN., 198:

> > 1.11

1952 PAGE 573