Cons. 4047 Rev. 10/60

## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. 45 N.R. 28W

|                            |                |                  |            | Marquette         |                  | COUNTY |
|----------------------------|----------------|------------------|------------|-------------------|------------------|--------|
| DESCRIPTION OF CORNER      | Section        | n corner for     | Sections 2 | 28-29 <b>-</b> 32 | 2-33             |        |
| CORNER MONUMENT            | l" pip         | e with 4" ali    | minum cap  |                   |                  |        |
| DATE MONUMENT PLACED AND W | I THE SSED _   | <u>. 1, - 10</u> | 11-13-61   |                   |                  | ····   |
| WITHESSES TO CORNER        | · <del>-</del> | 711 Tamarack     | (S28NBT)   | N310E             | 15 links         |        |
| N .                        |                | 6" Tamarack      | (S33NBT)   | S58°E             | 28 links         |        |
| 33                         |                | 4" Balsam        | (S32 NBT)  | S60°W             | 08 link <b>s</b> |        |
|                            | MD             |                  |            |                   |                  |        |
| CIRCLE CORNER REGISTERED - |                |                  |            |                   |                  | ·      |

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established at intersection of old blazed lines to east, west and south. Position of ledge 2.25 chs. south agrees with calls of notes. Several swamp edges and a stream to south also check well.

SURVEYOR'S SEAL

ONED Such DATE March
REGISTERED LAND SURVEYOR

Billy D. Buckler