Cons. 4047 REV. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced as set by John Hielala, Registered Land Surveyor. Found 5/8" Iron Pin and two Red Pine witnesses as noted at that time. Corner lies 22.0 Feet West of odd R.R. grade.

SURVEYOR'S SEAL

CIRCLE CORNER REGISTERED

Billy Q. Buckler

BILLY W. BUCKLER

DATE 7/29/1964

REGISTERED LAND BURVEYOR