## **MICHIGAN** DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T.45. NR 30 E.

DESCRIPTION	OF CORNER	Meander_Corner on South side of Sound Lake hetween Sections  MONUMENT_1" Pipe with L" Bress cap
DESCRIPTION WITTNESSES	TO CORNER	9r Cedar - N 76 Y - 73 Links
		_1AT Hemlock - S 12 F - 16 Links
DESCRIPTION II	N DETAIL AS	TO HOW CORNER WAS LOCATED AND IDENTIFIED OR

RESTORED.

This corner was pointed out to me by D. Zettle, Regional Forester, of Marquette. One original B.T. still in place, good condition.

Cerner was placed and witnessed October 7, 1952.

SURVEYORS SEAL