SURVEY & REMONUMENTATION

MAR 1 3 1998

Gerald W Corlson

Surveyor's Michigan License No._

MARQUETTE COUNTY

RECEIVED	FOR	

SECTION		R RECORDATION CERTIFIC			1997	DEC 26	PH 12	2: 48	3
For corners in MARQUETTE (County)	Filing Require	Corner Code #	Patricia d. Manley REGISTER OF DEEDS						
1. Public Land Survey	T_46N R_25W_ T_46N R_24W_ TR	M-8 A-8			REC	ISTER U	r Utel	15 V	8,
2. Property Controlling S	TR TR TR TR TR		LIBER		2 PAG	E 49	R File Nu	mher	
4. Lot No, Recorded		L.		· · · · · · · · · · · · · · · · · · ·	01 050	as samp	2 1 110 140		
5. Private Claims	· · · · · · · · · · · · · · · · · · ·		- A	В	D 1	FG	H I	J K	L
•			2	é	 5		-	2	···]
I. GERALD W. CARLSON	, in a field survey on DE	ECEMBER 18TH , 19 97 , do	3 -						
hereby state that under requirement	s of P.A. 74, Michigan F	P.A. of 1970, the corner points	s 4		8	<u> - </u> -	-10	11	12
mentioned in lines 1 and 2 above w required in the current manual of surve									-
Bureau of Land Management or by	a decree of a Court of La	aw and/or that the comer points	s ⁶	—1 8 —	17—	16	-15	14	13
mentioned in lines 3, 4 and 5 above v Land Surveyors or by a Decree of				. 19	20	21	_22	23	24
recovered, found as expressed below:		, , , , , , , , , , , , , , , , , , , ,	9 -						
NOTE: Not more than 2 corners,	all in the same town an	d range, may be recorded		30	29	28	27	26	25
on this certificate.	•	•	11					-	
A. Description of original monume	ant and acceptate and	or subsequent restoration:	12	31	32—	-33	-34	35	36
M-8: Quarter Corner common to Se	ection 24, T46N-R25W.	and Section 19, T46N-R24W.	. 13 [[]					_Ll	
1844: William A. Burt's original sur post referenced by:	rvey notes describe the	corner monument as a wood				BY PEE	R GRO	UP	
18" Sugar S30E, 38	L 14" Fir	N58W, 04 L		P.A.	345 0)F 1990	3	•	a
No further corner information avail-	ahla			<i>حر۔</i> DA1	an	12/	JUGS		_
No further comer intomiation availa	ibie.			DAI			2/		_
B. Description of corner evidence M-8: 1997: No original corner evid N.E. Corner of Section 36 to the N Line. Various cruisers paint lines, line measured 136 feet short from decided at the December 15, 1997 South of the East 1/4 Corner of Se Section 1 were proportioned to the East-West position of the N.E. Corn This put a slight bend in the Straig N.E. Corner of Section 36 to the N. The distances West to the N.W. and GLO distances.	ence found. Survey co.E. Corner of Section 1. Illocation posters and GL the GLO measurement of Peer Group meeting to action 1 and the N.E. Corner of Section 1. The corner of Section 1.	ontrol was established along the No evidence of existing corner to LO Line Calls were tied in along from the N.E. Corner of Section proportion the East 1/4 Corner of Section 1. The remain 36. Each 1/2 mile distance Walaced 231' West (GLO - 3.5 cler of Section 13 was placed 29. The remaining stream calls from 13 and the South 1/4 Corner of Section 14 and 15 a	ne East Ters was go the end of th	Fowns found tire 5 the N. tion 1 corners 2.72' f the cest of nely w	along amile ro E. Corr between South by using enterling this cangell to t	this 5 milute. This her of Selen the stoof the Eg this prose of the loulated she propo	le section 5 mile ction 1. ream can ast 1/4 oportion stream straight rtioned	on of sect line of the corner	Rangion of was 6' ner of East. From ers.
C. Description of monument for of M-8: 1997: Set a 2 3/8" O.D. alur stamped to identify the corner. Mc Established new references (to set 7" Y. Birch N30W, 21" W. Birch (Forked) N62E, 8" Y. Birch S31E, 13" Maple S15W,	minum pipe capped with onument is 0.6' below of d.h. nails}. 17.16' 68.55' 15.72' 27.42'	a 3 1/4" diameter aluminum t	ablet M	arquet			ey Mon	umer	nt V
Note: Bearing trees have painted fa	ice, butt. and side nail b	lazes,			Ex.	•	LD W	***	E.
d.h. measuring nails, and stamped Bk. 13, Pg. 63-66					* 1	SUR'	RLSON VEYOR No. 589		***