DEC 2 1 1993

	COMMISSION
--	------------

## LAND CORNER RECORDATION CERTIFICATE

LIBER 283PAGE 346

For corners in	COMMISSICA	Filing Require	ement of Act 74, Mich. I	P.A. 1970	£101-1		* ****		
Missaukee	ee	Located In.	Corner Code ##	1	AISSAUKE				כ
1. Public Land	d Survey	T 21N R 7W T R T R T R	M-13	(	-100 D	E 13	1993 FL	1/AM	
<ol> <li>Property Control in Section</li> <li>Miscellaned Property in</li> </ol>	S ous	T R T R T R			r of Deeds				
5. Private Clair	ms		ber 8 <sub>19</sub> 93	2 3	A B C D	E F	G H	J K L	
do hereby certify to in lines 1 and 2 a current manual of Management or by above were in corrections.	that under requiremer above were in conform f survey instructions or y a decree of a Court on formance with the rulestablished, re-estable	nts of P.A. 74, Michigan P.A. mance with regulations an of the United States Depart of Law and/or that the corne les of the Michigan Board o	of 1970, the corner points men d rules therefore as required ment of the Interior, Bureau o r points mentioned in lines 3, 4 f Land Surveyors or by a Decr nonumented, recovered, fou	tioned 6 in the 7 If Land 7 and 5 8 ee of a		21-		23 - 2	3 - 4
on this	certificate.		id range, may be recorded	j 11 f2 f3	31 32	33-	34	35 30	- -

- M-13) 1837 GLO Section post by John Brink, Deputy Surveyor
  Beech 10 N 23°E 25, Beech 0 N 31 1/2° W 56

- M-13) 1893 Beuthien survey in Section 36: Corner was used but no information given
- M-13) Beuthien Notes, Southeast corner of Township: Beech 10 N 23° E 25, Beech 9 N 31 1/2° W 56
- M-13) 1989 D. Porter Survey: Found wood stake and channel Iron 4' below grade, raised with Iron and
- Description of corner evidence found and/or method applied in restoring or reestablishing corner:
  - M-13) Section corner common to Section 36, T21N, R7W and Section 31, T21N, R6W

Found Porter Iron. Corner falls ±6' West of centerline of road to North, ±2' South of centerline of road to East and ±2' North of centerline of road to West. This corner is accepted as a careful and faithful perpetuation of the position of the original corner.

- Description of monument for corner and accessories established to perpetuate locating the position of the corner:
  - M-13) Found 1/2" Iron: Set monument box and added Missaukee County monument to Iron

S 01° W - 19.05 - Set pk nail in West end of culvert

N 87° E - 77.18 - Set pk nail in North end of culvert N 63° E - 48.77 - Road sign post N 58° W - 63.08 - Top center of phone pedistal

Peer Group Reviewed and Approved

J. Dean Geers, Missaukee Co. Representative

Signed by	Juice.	Date 12/8/93	
Surveyor's Michigan License No.	33977		