i ibei	12	_Pago.	31	
641561		~ 5 ~.		_

Montmorency County Remonumentation

LAND CORNER RECORDATION CERTIFICATE

Ĺ	j'S	?		5
		•	٠,	

	•			
		Filing Requi	rement of Act 74, Mich. P.	A. 1970 달 골호
Fo	r corners in			> 1 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8
	MONTMORENCY	Located In:	Corner Code ##	c to the second of
	(County)	RUST TWB.		AND STORES
1.	Public Land Survey	T <u>29N</u> R <u>4E</u> T <u>29N</u> R <u>4E</u> T R:	A-10 A-11	A P P FED
2.	Property Controlling	TR STR		PH '93
	in Section	S T R		
3.	Miscellaneous	S T R		Register of Deeds Stamp & File Number
	Property in Sec.	SR		
4.	Lot No	, Recorded Plat		A B C D E F G H I J K
5.	Private Claims		· · · · · · · · · · · · · · · · · · ·	
				· - 6 - - 5 - - 4 - - 3 - - 2 - - 1

_ , in a field survey on August - September do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

West 1/4 Cor., Sec. 30, T.29 N., R.4 E. Orig. Post by Lewis Clason - Nov. 1839 S52W-31 lks(20.46')Tam, N28W-36 lks(23.76')Tam 1971-Un-Rec Sur by N. Caldwell - Set Conc. Mon. 1971-Un-Rec Sur by N. Caldwell - Set Conc. Mon.
Does not Indicate Corner Evidence Fnd or Nthd Used
S15E-25.0'-3" Map, S75W-29.3'-3" Map, N30W-33.0'10" Oak
NO ACT 74 RECORDED FOR THIS CORNER

A-11 SWMCor. Sec. 30 & NW Cor. Sec. 31, T.29 N., R.4 E. Orig. Post by Lewis Clason - Nov. 1839

S66W-29 lks(19.14')Hem, N65W-42 lks(27.72')Maple
1971-Un-Rec Sur by N. Caldwell - Placed 1/2" Iron &
Cap in Fnd 1½" Pipe - Does not Indicate who:Set Pipe
\$12E-43.3'- 5" Maple, \$5.58W-31.6'- 10" Oak
N20E-63.2'- 6" Birch, NORTH-33.0'-DNR Mkr Post
NO ACT 74 RECORDED FOR THIS CORNER

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-10 West 1/4 Cor., Sec. 30, T.29 N., R.4 E. Fnd. Rec. Conc. Mon. (Caldwell Sur) S.15°E - 25.0'--8" Maple (Rec) S.75°W - 29.3'- 3" Maple (Rec) (Now Dead) N.30°W - 33.0'-10" Oak (Rec) NO ORIGINAL CORNER EVIDENCE FOUND

A-11 SW Cor. Sec. 30 & NW Cor. Sec. 31, T.29 N., R.4 E. Fnd. Rec. Irons& Cap in 1%" Pipe (Caldwell Sur)
NORTH - 33.0' - DNR Mkr Post?(Rèc)
N.20°E. - 63.2' - 6" Birch (Rec) NO ORIGINAL CORNER EVIDENCE FOUND

Approved by Montmorency County Peer Review on Sept. 24, 1993; as a careful and faithful re-establishment of the position of the corner.

Approved by Montmorency County Peer Review on Sept. 24, 1993, as the best available evidence of the original corner.

□. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-11 SW Cor., Sec. 30 & NW Cor Sec. 31, T.29 N., R.4 E. A-10 West 1/4 Cor., Sec. 30, T-29 N., R.4 E.

Set Mont.CCo. Re-Mon Cap on Fnd. Conc. Mon. S.75°E. - 7.00 - Set Tag SN Sd. 8" Maple S.15°E. - 25.12'- Set Tag E. Sd. 6" Maple N.50°W. - 11.30'--SettTaggSN Sd. 6" Twin Maple N.30°W. - 33.34'- Set Tag E. Sd. 18" Oak Fnd. Cedar R.T. Post Along Side Corner Set Mont. Co. Re-Mon Cap on Fnd 1/2" Iron in Pipe Corner is in C.L. E-W Dirt Rd. (McIntire Rd) Corner is ±3' W of Fnc to S.

NORTH - Set Tag E. Sd. Cedar R.T. Post

N.20°E. - 63.47' - Set Tag E. Sd. 12" Birch

S.60°E. - 33.24' - Set Tag SW Sd. 8" Maple S.10°E. - 16.28' - N Face of Steel Fnc Cor Post N.55°W. - 28.62' - Set Tag SW Sd. 8" Poplar HIGAN

NOTE: All Witnesses Marked with Db1. Headed Nails & I.D. Tag #25852, unless otherwise noted

Consider Consider Section of section in the regarded Activities for the medicate in the conte

-urveyor's Michigan License No. . 25852

Date Vec. 23, 1993

FREDERICK J. KING PROFESSIONAI SURVEYOR Nn.

25852 POFESSIO