COMMISSION

LAND CORNER RECORDATION CERTIFICATE, OH. 1813 21 PM 3 28

For corne	are in	Filing Requ	uirement of Act 74, Mich. P.A. 1	1970	illi CI			0
Neva)	/go	Located In:	Corner Code ##	m	anten	 1	/wgs	704 P
 Prope in Se Misce 		T 16 N R 13 W T R T R T R R T R S T R S T R S T R S T R S T R		,	001	PAGE	64	
4. Lot N	0.	Recorded Plat			_			
					3 C D	T T	G H	JKL
				3	5 -		3-	1 2
do hereby in lines 1 a current ma Manageme above were Court of	cerlify that under re and 2 above were anual of survey inst ent or by a decree of e in conformance w Law; established,	equirements of P.A. 74, Michigan P in conformance with regulations ructions of the United States Dep f a Court of Law and/or that the co rith the rules of the Michigan Boar	December 10, 19 93 A. of 1970, the corner points mentioned and rules therefore as required in the partment of the Interior, Bureau of Land rner points mentioned in lines 3, 4 and 5 d of Land Surveyors or by a Decree of a e-monumented, recovered, found as	6 — 13 7 — 8 — 13 9 — 1	31720	9	15-22-	14 1
expressed		corners, all in the same town	and range, may be recorded	10 -30	29-	2'8	2'7-	262
	on this certificate		:	123	132-	33	34~	353
A. Desci	ription of original	monument and accessories a	and/or subsequent restoration:	13		1_1	<u> </u>	
		y, John Hodgson, G.L.O.	1902 - Delos Anderson, Co., Surve	yor 1939) – s. Mi	ddlebro	ook, U	SFS
	#1 24" Pine \$66' #2 &" Pine \$21'		Found old Gov't Corner #3 24" Pine \$66 ⁰ W 10 Links (#1)		d Railro ISFS Post			ks
	#E O THE HET	W EJ CHING	#4 8" Pine N21 ^O W 25 Links (#2)		0,0,0			
	S.E. Corner, Se I found Surveyor #2 Gone, #3 Four in good condition	evidence found and/or metho ction 13, T16N, R13W, Newaygo r Griffin's Concrete Monument nd remains of stump, #4 Gone, on, #9 Found in good condition	d applied in restoring or reestablish Co., Mi. Condition of the recorded with #5 Gone, #6 Found in good condition, #10 Measured 1881.8', #11 (not good condition, #15 Found in good condition)	esses are: ion, #7 Foun checked), #	#1 Found	d condi	tion,	#8 Found
C. Descr	iption of monume	ent for corner and accessorie	s established to perpetuate locatin	ng the positio	on of the	corner	.	•
M-7 -	S.E. Corner, Sec	ction 13, T16N, R13W, Newayso	. Ca., Мі.					
	the original con 10" Maple S71 ^O E 7" Maple N55 ^O W 7" W. Oak S40 ^O t			s a careful ,	and fait	hful pe	erpetua	NORMAN L. OCHS
	3/2	LO 12.	a Dec	ember 2	21. 19	992 M		22439
Signed by Norman		LS 22439	Oato		·		THE CALL	DIAND
•	Michigan Licens wed by Peer Revie	D 91		I APPROVED BY MICH	IIGAN STATE E	BOARD OF LI	AND SURV R	EYDRS, JAN. 28. IEVISED MAY 14. BEVISED JAN.

Approved by Peer Review Group Norman Ochs, County Representative

CONTINUATION OF "A"

<u> 1955 - George Blass, LS 5489</u>

Monument - Railroad Rail

6 14" B. Oak N30°E 23.30'

7 16" B. Oak S25°E 7.10

8 7" W. Oak \$40°W 24.75'

9 3" Maple N55°W 18.95

#10 M.C. East side of Pettibone Lake

West 1882.58'

#11 S.E. Cor. Sec. 24 is s1⁰20'22"W 5273.56'

1972 - Robert A. Griffin, LS 13584

Found Railroad Rail and replaced with standard USFS Concrete Monument

#12 6" Maple S71^OE 25.17'

#13 Pine Post South 1.3'

#14 7" W. Oak \$400W 24.75'

#15 3" Maple N55°W 18.95'