-	Lufford
	DECODD ATION OF STILL

			NER RECORDATION CER	TIFICATE	25836	
For corr	ners in	Filing Requ	irement of Act 74, Mich. F	A. 19710 er 21021. 19.00 Misc	B PAGE 445 RECORDING	
Oakla				\$2,00 REMONI	IMENTATION 08:21:21 A.M. RECEIP	T# 6667
	(County)	Located in: C	orner Code #	BATH REC	ORDEB - NAKLAND COUNT	Y
4 Bull	,	TON # 75		6. WILLIAM	CADDELL, CLERK/REGIST	EK OF BECDS
T. Publ	ic Land Survey	T <u>2N_R_7E</u> TR	<u>A-4</u>			
•		T R	SURVEY &		Compliance with	
		T_R_RE	MONUMENTATION		ACT 345, P.A. 1990	
	erty Controlling	S TR S TR	**** 0.1 0000	APPROVI		JK
3. Misc	ellaneous	S TR	MAR 21 2000	OAKLAN P	D COUNTY REMONUN EER GROUP COMMIT	MENTATION TEE
Prop	erty in Sec.	S TR	0503101		er of Deeds Stamp & I	
	,	`	SECTION			
4. Lot N	lo, Record	ed Plat				
5. Priva	te Claims			¹ÎŢŢ	DEFGHI	
		•		3 5	_51131	— 2 — 1 - 1
I Grant	J. Ward, R.L.S.	in a field survey on July 29	3 , 1999 do hereby state that	- 1 1 1		
requirema	ents of P.A. 74, Michigan	P.A. of 1970, the corner points a	mentioned in lines 1 and 2 above w	vere in	— 8—— 9———10——	
Conformation United Sta	nce with regulations and re ates Department of the Int	ules therefore as required in the cu terior. Bureau of Land Managemet	irrent manual of survey instructions nt or by a decree of a Court of Law a	orme i	-171615	-1413-
that the c	orner points mentioned in	lines 3, 4 and 5 above were in co	onformance with the rules of the Mic stablished, re-established, monum	higan		14-13-
recovered	, found as expressed belo	w:	naviolicu, ie-estavisijou, iliviluili	8 19	202122	2324
NOTE:	Not more than 2 come	rs, all in the same town and ran	rea may be recorded	9		
	on this certificate.		go; may no recorded	10-30-	_292827	_2 6 25_
				11		
	,	`		12 -31	32 33 34	_3536_
A. Desc A-4	ription of original monu Post, per G.L.O. I	ument and accessories and/o Notes.	r subsequent restoration:	. 13		
	,		•			
-			,		\mathcal{N}_{n}	
					66	
B. Desc A-4	cription of corner evide West 1/4 Corner	nce found and/or method app of Section 7, T. 2 N., R.	olled in restoring or reestablishing 7 E.	ng corner:	K	
	Previously Unreco	orded.				
	·					
			rolling monument is accep	oted as a careful	and faithful	
	determination of t	the position as indicated.	•			
					•	
C. Descr	iption of monument for	corner and accessories esta	blished to perpetuate locating t	he position of the co	orner:	•
	THE OF MINUTES	A-4 Set N 25 ° E	: 5/8" Iron Rod and Remo 56.78' Set MAG Nai			
	14 3000000000000000000000000000000000000	N 25 E	Asphalt Road		tation bisc in -	
	GRANT J. S	S 65° E	24.97' Set MAG Nai	l & Remonumen	tation Disc in	
*	LAND SUBVEYOR	★ S 60° W	Asphalt Road 20.57' Set MAG Nai Asphalt Road	l & Remonumen	tation Disc in	
A ROS	SURVEYOR NO. 22445	N 30° W	62.78' Set MAG Nai Asphalt Road	l & Remonumen	tation Disc in	
A STATE	Chi In O W	South	12.05' East 1/4 Con		. 2 N., Ř. 6 E.	
Signed by	Marie Control	ct IMC		Α.	2 1000	
•	Michigan License No	22445	Date _	August	2. 1999	
ouiveyors	o whengan license No:	22445				

JULY 20, 1999

Corner Code: A-4

DOSSIER FOR: THE WEST 1/4 CORNER OF SECTION 7, MILFORD TOWNSHIP, T 2 N, R 7 E, OAKLAND COUNTY, MICHIGAN. Prepared under contract with the County of Oakland Under Act 345 of the Public Acts of 1990.

HISTORY:

This Corner was not originally set by the Government Surveyor and has not been previously recorded.

COLLATERAL EVIDENCE:

We set a 5/8" iron rod and remonumentation cap midway between the Southwest and the Northwest Corners of Section 7 and on the Township Line 12.05 feet North of the East 1/4 Corner of Section 12 of Brighton Township. This Corner lies 33.8 feet North of a test track. There is no evidence of occupation in any of the cardinal directions from this Corner. We did not set a concrete monument due to buried debris. We agreed with the recorded distances from the East 1/4 Corner of Section 12 of Brighton Township to the adjacent Section Corners of Brighton Township within 0.2 feet. We searched at least 50 feet in each direction for other stakes and found none that might represent the Corner.

SURVEYOR'S RECOMMENDATIONS:

This corner location, although not established by an original government survey, is accepted by the Contractor and is a careful and faithful determination of the position as indicated. Therefore, I recommend that the Peer Review Group accept this Corner as monumented, with the references as shown on the enclosed form prepared according to Act 74 of the Public Acts of 1970.

Grant J. Ward, R.L.S. License No. 22445

SURVEY & REMONUMENTATION

MAR 21 2000

SECTION