LIBER 21028 - 595

LAND CORNER RECORDATION CERTIFICATE

25911

	Filing	g Requirement of Act 74, Mich. P	
For corners in Oakland	Located in:	Corner Code #	\$9.00 MISC RECORDING \$2.00 REMONUMENTATION 01/27/2000 08:21:22 A.M. RECEIPT# 660 PAID RECORDED - DAKLAND COUNTY
(County)			G. WILLIAM CADDELL, CLERK/REGISTER OF
1. Public Land Survey	T <u>2N</u> R_ TR_	7E <u>K-5</u> SURVEY &	
	TR_	REMONUMENTATION	Compliance with ACT 345, P.A. 1990
Property Controlling in Section Miscellaneous	s TR s TR s TR	MAR 21 2000	APPROVED ON: 7-14-GG JK OAKLAND COUNTY REMONUMENTATION PEER GROUP COMMITTEE
Property in Sec.	s TR_	SECTION	Register of Deeds Stamp & File Numb
4. Lot No, Reco			A B C D E F G H I J K 2 6 5 4 3 2 2 3

IGrant J. Ward. R.L.S... in a field survey on <u>December 9</u>, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- K-5 Post, per G.L.O. Notes.

29

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- K-5 Northeast Corner of Section 14, T. 2 N., R. 7 E. Found 5/8" Iron Rod.

Previously Recorded in L. 6347 P. 171 (1), L. 12207 P. 882 (4) and L. 12208 P. 635 (2) of Oakland County Records.

(n) Indicates the number of references that confirms this corner by dimensional tie.

This corner location is accepted by the contractor and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

 C. Description of monument 	tiot coulet sud accessorie	20 00(mpilotito to	po,p
	K-5 Set Mo	nument and F	Remonumentation Cap.
2000000	N 05° E	15.00'	Set 60d Nail & Remonumentation Disc in Top of
1		07.401	Guardrail Post. Set 60d Nail & Remonumentation Disc in West
GRANT J.	§ \$ 10° E	88.19'	face of Utility Pole.
WARD LAND	*	16.99'	Set 60d Nail & Remonumentation Disc in Top of
SURVEYOR	★ \$ 35° W	10.55	Guardrail Post.
NO.	N 80° W	31.34'	Set 60d Nail & Remonumentation Disc in North
22445	N OO W	0	face of Utility Pole.
A PEO	N 85° W	33.19'	Found Monument.
TAND	The		Date (ulv. 1.2. 1999
Signed by	an		Date

Surveyor's Michigan deense No. 22445

JULY 3, 1999

Corner Code: K-5

DOSSIER FOR: THE SOUTHEAST CORNER OF SECTION 11, MILFORD TOWNSHIP, T 2 N, R 7 E, OAKLAND COUNTY, MICHIGAN. Prepared under contract with the County of Oakland Under Act 345 of the Public Acts of 1990.

HISTORY:

This Corner has been accepted and used since before 1972, as evidenced by a recording under Act 74 of the Public Acts of 1970 by Robert A. Campbell, Jr., Surveyor as recorded in Liber 5896, Page 160.

COLLATERAL EVIDENCE:

This Corner lies 14 feet West of the Centerline of Burns Road and 2.5 feet East of a guard rail. There is a concrete monument 33.19 feet West of the Corner. We set a concrete monument and remonumentation cap in place of a 5/8" iron rod we found. We measured 2.94 feet less and 3.24 feet more than the recorded distances to the West and South 1/4 Corners of Section 12 respectively. The measured dimension to the East 1/4 Corner of Section 14 is 1.81 feet longer than the recorded distance.

We searched at least 50 feet in each direction for other stakes and found none that might represent the Corner.

SURVEYOR'S RECOMMENDATIONS:

This corner location is accepted by the Contractor and is generally accepted by Professional Surveyors as the best available evidence of the position of the original Corner. Therefore, I recommend that the Peer Review Group accept this Corner as monumented, with the references as shown on the enclosed form prepared according to Act 74 of the Public Acts of 1970.

Grant J. Ward, R.L.S. License No. 22445

SURVEY & REMONUMENTATION

MAR 21 2000

SECTION