LIBER 20793

# LAND CORNER RECORDATION CERTIFICATE

	Filing Requirement of Act 74, Mic	h. P.A. 1970	
For corners in		1	416573
Oakland (county)	Located In: Corner Code # Bloomfield Township	\$3.0 \$2.0 11/1	ER 20793 PAGE 723 DO MISC RECORDING DO REMONUMENTATION 16/1999 08:01:31 A.M. RECEIPTI
Public Land Survey	T 2N R 10E A-1 T R T R	6. 0	D RECORDED - OAKLAND COUNTY WILLIAM CADDELL, CLERK/REGISTER Compliance with C 345, P.A. 1990
Property Controlling S	T R T R T R T R T R T R T R T R T R T R	APPROVED ON:	
4. Lot No, Reco	orded Plat	A 8	CDEFGHIJKI
5. Private Claims			
requirements of P.A. 74, Michiga were in conformance with regular instructions of the United States decree of a Court of Law and/or conformance with the rules of the	field survey on November 8,1999, do hereby cent P.A. of 1970, the corner points mentioned in lines tions and rules therefore as required in the current mean population of the Interior, Bureau of Land Managethat the corner points mentioned in lines 3, 4 and 5 are Michigan Board of Land Surveyors or by a Decreal, monumented, re-monumented, recovered, found	1 and 2 above 4 gamual of survey a above were in 6 above were in 6 as expressed 8 19	8 - 10 - 11 - 17 - 18 - 15 - 14 14 22 - 23 21 - 23 - 23
A. Description of original mo	nument and accessories and/or subsequent re	estoration:	29 28 27 26
	urvey. Unable to read witnesses. ded at Oakland County; McCoy 1999.	11 12 31	32 33 34 35
B. Description of corner evid reestablishing corner:	ence found and/or method applied in restoring	or 13	<del></del>
Recovered a concrete mo with monumentation found West Bloomfield and Bloo	nument with Oakland County Brass Cap stam d in Sylan Lake Subdivision #3. This corner is omfield.	ped # 31606 at this loc common to the townsh	ation. Validated location ips of Pontiac, Waterford,
C. Description of monument	for corner and accessories established to perp	petuate locating the pos	sition of the corner:
Found Oakland County Re	emonumentation Brass Cap stamped #17623.		
S 05°E 49.88' PK nail eas S 25°W 17.10' PK nail eas S 15°W 48.45' PK nail eas	it side power pole with Oakland County Remor st side 32" Maple with Oakland County Remon st side 4" Cedar.	numenation tag#17623 numentation tag #17623	3.
S 60°W 60.40' northwest	corner garage house #1497 Avondale.	•	24
1			R
			alltitff
RE	ROTEN .	William S. A. T.	OF MICHIGAN
j.s.G	R 21 2000	KAI PHO	PELCZAK & PESSIONAL & PESSIONA
S	ECTION	JO KAI	No. 24598 FESSIONAL
Signed by July (	Kapeleyak Date	11/9/99	
Surveyor's Michigan License	No. <u>24598</u> FORM	/ / APPROVED BY MICHIGAN STATE E	BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

**AUGUST, 1997** 

### OAKLAND COUNTY REMONUMENTATION

**CORNER A-1** 

Dossier for: The northwest corner of Section 6, T. 2N., R. 10E., Bloomfield Township, Oakland County, Michigan.

#### G.L.O. Survey History

Bloomfield Township was originally surveyed by Joseph Wampler D.S. 1817. The township was subdivided into sections with closing corners set on North and West Township lines. Posts were originally set as noted on enclosed Oakland County Land Recordation Certificate.

#### Existing Field Evidence

There is one LCRC recorded at Oakland County; McCoy 1999.

We recovered a concrete monument with Oakland County Brass Cap stamped # 31606 at this location. Validated location with monumentation found in Sylan Lake Subdivision #3. This corner is common to the townships of Pontiac, Waterford, West Bloomfield and Bloomfield.

## Recent Corner Record, Survey and Measurement Evidence

A-1 to B-1

2643.37' meas.

A-1 to A-2

3260.27' meas.

Note: All measured distances represent grid distance SPC MI South Zone.

#### Surveyor's Recommendation

I, therefore recommend that the Oakland County Peer Group accept this corner as the best position of original corner in regard to evidence found.

oseph C. Kapelczak, P.S/#24598

PARTEY &

MAR 21 2000

SECTION