## SURVEY & REMONUMENTATION

MAY 2 4 2000

LIBER 21119 ~ 637

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Regulrement of Act 74, Mich. P.A. 1970

51705

			BER			PAGE		; ;			
For corners in		1 45	00	REMI 12001	HUM OP	ORDI NTAT 36:2	ION 7 P.1	. R	CEIP	T# 1	4203
Oakland	Located In: Corner Code #	I D6:	T N	20	ากลา	NFD -	nok:	AND L	JUNI	1	F DEEDS
(county)	Bloomfield Township									•	
1. Public Land Survey	T <u>2N</u> R <u>10E</u> <u>L-1</u> T R										
	<u>TR</u>	į					77.7	_	<b>_</b>		
2. Property Controlling S	T R		* * . ::	au. Tug		<b>2-7</b>	, <b>90</b>		77 l 77 T		
in Section S	on <u>S</u> T R										
3. Miscellaneous S Property in Sec. S	T R	Register	of	Dee	ds (	Stan	1p &	File	Num	ber	
							,				
4. Lot No, Reco	rded Plat		A	B	С	D E	F	G F	<u> </u>	j	KLA
5. Private Claims		2	-	.	-	-	-   -	<del> </del>	+	-2-	<del>-</del>
I, Joseph C. Kapelczak, in a field s	survey on July 12.1997, do hereby certify that	ınder requirements 3	-	+	-	$\dashv$	+	╅╌╅	+	+-	<del> - -</del>
of P.A. 74, Michigan P.A. of 197	O, the corner points mentioned in lines 1 are not rules therefore as required in the current	d 2 above were in 4	-	· }		•	<b> -</b> -	† 'i	+	-11 	4-12-
instructions of the United States	Department of the Interior, Bureau of Land M	anagement or by a	-	+-	1	-	$\dashv$	<del>  </del>	_		<del>                                     </del>
decree of a Court of Law and/or the	hat the corner points mentioned in lines 3, 4 a	nd 5 above were in 🥫	╟	18	<del>  </del> 1	7-+	-16-	<del> -</del> "	┝╼╋╌	-14-	13-
conformance with the rules of the	e Michigan Board of Land Surveyors or by a D , monumented, re-monumented, recovered, f	ecree of a Court of 7	′├−	+	-	-	+	1 1	+	+-	<del>                                     </del>
below:	, mortalienteu, ib-monumenteu, 1600vereu, i	ania as expresses	<b>-</b>	19	-2	0	-21-	<del>  _2</del> ;	╌┼	-23-	+-24-
		\$	<b>'</b> -	╂	╂	-	+	1-	+		++-
A. Description of original mon	ument and accessories and/or subseque	nt restoration:	<b>-</b>	-30	2	-	-2 <b>5</b> -		<u>'</u>	-26-	-25-
Set post in 1817 G.L.O. sui	rvey.	{1	-	╂┈	┼		+	╀╌┤	-+	+	++-
There are no LCRC's recor	rded at Oakland County.	. 12	1	31-	-3	2-	33	1-3	╌┼	-35-	36-
B. Description of corner evide reestablishing corner:	nce found and/or method applied in resto	ring or	3 L	L	<u>.                                    </u>			-1			<del></del>
	•	,				_					ut.
line of CHAPEL HILL ESTA	und at this location. This comer was re-e ATES #1 and the south line of AUBURN F veen L-13 and M-13 Pontiac Township an	IEIGHTS MANOR.	In	doll	ng s	o, tr	is co	rner	tne is o	non n the	:n }
C. Description of monument for	or corner and accessories established to	perpetuate locating	the	e po	sitio	n of	the	come	er:		
Set 5/8" iron with Oakland	County Remonumentation Brass Cap sta	mped #24598 in ne	w r	non	ume	ent b	ox.				
Set Witnesses:	?			-							
S 18°E 108.51' Mag nail wi S 19°W 47.71' Mag nail wit N 39°W 65.35' Mag nail wit	h OCRT #24598 southeast side 14" Maple ith OCRT #24598 west side 18" Willow. th OCRT #24598 west side 12" Maple. th OCRT #24598 southwest side 16" Map ron in monument box L-13 Pontiac Towns	le.						1	MA		



Signed by Surveyor's Michigan License No. 24598

Date

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983