SURVEY & REMONUMENTATION

UBER 17055 PO 751

MAR 0 4 1998

OCOTION:	LAND CORNER RECORDATION CERTIFICATION FILLING Requirement of Act 74, Mich. P.A. 19	70
SECTION SECTION		
Oakland Located In:	Troy Twp. Corner Code #	
•	2N R 11B L-7 R R R R	Compliance with ACT 345, P.A. 1999
2. Property Controlling S T in Section S	R	APPROVED ON: 2-26-97 TS OAKLAND COUNTY REMOVED THAT IS PEER GROUP COMMITTEE Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat 5. Private Claims		A B C D E F G H I J K L M 1 2 6 5 4 3
conformance with regulations and rules therefore United States Department of the Interior, Bureau that the corner points mentioned in lines 3, 4 at Board of Land Surveyors or by a Decree of recovered, found as expressed below:	Survey on 12/13, 19 96 do hereby state that under the corner points mentioned in lines 1 and 2 above were in a servery instructions of the ser	6 18 17 16 15 14 13
NOTE: Not more than 2 corners, all in the on this certificate.	same town and range, may be recorded	10 30 29 28 27 26 25 11 32 33 34 35 36
1817-GLO Wampler, D.S.; Set Post 5" 1.) 1974-Fraus, PS #17089; LCRC L.6	daccessories and/or subsequent restoration: Ironwood S29°E 5 Links; 5" Lynn N1-1/2°E 5 Links; 310, Pg.733 - Fnd P.K. Nail ded Survey - Object found not stated, no witness ded Survey - Object found not stated, no witness	ses 13 MAR 97 11:48 A.M. RECEIPT# 105A
1997 Kennedy Surveying, Inc Ken of Wattles Road extending to t	d and/or method applied in restoring or reestablishing nedy, PS #17623 - Fnd 5/8" Iron Rod 4" below the the East & West, which has a bituminous surface. I	A fence, tree and plat line extending to the North
to recover and verify the loc	VERNON ESTATES", L.116, Pgs. 13-17 & "OLDE FORGE ration of the found $5/8$ " Iron Rod.	che che
I accepted the found 5/8" Iron Rod as the best evidence of the original corner position.		er position.
Field measurements between se C. Description of monument for corner	and accessories established to perpetuate locating the	re position of the corner:
L-7 I replaced the found 5/8" Iron #17623 in a new Monument Box S03°E 68.10' Set PK & Remon W S64'W 89.46' Set PK & Remon W M63°E 83.40' Top Nut on Fire N49'W 97.98' Set PK & Remon W	n Rod with a 5/8" x 24" Iron Rod W/2" dlameter Dr asher West face 12" Oak asher NW face 11" Ash Hydrant asher SW face Power Pole	ass cap scamped constant country
The selected location is accepted position of the original corner.	by me and is generally accepted by Professiona	17623 S
Signed by	Date_	2.27-97
Surveyor's Michigan License No	1000	

SURVEY & REMONUMENTATION

UBER 17055 PG 752

MAR 04 1998

SECTION

FIELD HEASUREMENTS BETWEEN

L-7 to K-7

GLO = 39.22 chains or 2588.52 Ft.

MCS 2646.50 Ft. No date stated

M. Baldwin, PS #1298 (1926) 2645.30 Ft.

"MT. VERNON ESTATES" + 20-13-351-023 = 2644.76 Ft.

"OLDE FORGE SUBDIVISION" + "SUPERVISOR'S PLAT NO. 19", 2644.93 Ft.

GPS-MEA 2645.24 Ft.

<u>L-7 to M-7</u>

GLO = 39.22 chains or 2588.92 Ft.

M. Baldwin, PS #1298 (1925), 2606.20 Ft.
"SUPERVISOR'S PLAT OF FORSYTH ACRES", 2606.56 Ft.
"SUPERVISOR'S PLAT OF BROADACRES SUBDIVISION", 2606.56 Ft.
"EYSTERS DEQUINDRE SUBDIVISION", 2606.56 Ft.
GPS-MEA 2606.73 Ft.