

MAY 24 2000

LIBER 21146 096

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970,

\$9.00	MISC RE REMONUM	CORDING FNTATIO	N	proceed	n 429	E 4 A
BOTB	RECOR	ขะม - ถ	aki an	RECEIPT D COUNTY /REGISTE		
		ipliance :				
	ACI.	345, P.A.		~1)		

For corners in		£5	AA E	ENDN	KECORI IMENTA LO:58:	TION P7 A.	.M!	RECEI	PT# 1	16518	r				
Oakland	Located In: Corner Code #	l BA	T PA	1/1.17	RDED Caddel	- 1111	LI MNH	1.131124	t 1 2						
(county) Rose Township					J,12 & 2.	,									
1. Public Land Survey					Complicate with ACT 345, P.A. 1990 / PPROVED ON: //- 3() · 9(5/) / AKLAND COUNTY REMONUMENTATION										
2. Property Controlling S_	T R	- JAKLA	AND PE	COUI	NTY F ROUP	(KMI) MOX)	的是"被 "被害""是	enti El	\$ 33 to -	-					
in Section S_	TR	_													
3. Miscellaneous S_ Property in Sec. S	T R T R T R T R T R T R T R T R T R T R	Register	r of l	Deed	is Sta	amp	& File	e Nu	mbe	ŀſ					
rioporty in oco.	· ·	-	·												
4. Lot No. Re	ecorded Plat					٠	1			3	det i				
			<u>A</u>	B (D	Ef	<u> </u>	<u> </u>	!]	K	<u>L</u>				
5. Private Claims			2	 	<u> </u> 5	╀╌┋	+	- ş —	₂		- ļ -				
requirements of P.A. 74, Michiwere in conformance with regu	a field survey on <u>February 26, 1998,</u> do he gan P.A. of 1970, the corner points mentioned lations and rules therefore as required in the c	d in lines 1 and 2 above current manual of survey		,	8			-10			-12-				
decree of a Court of Law and/o	tes Department of the Interior, Bureau of Lan or that the corner points mentioned in lines 3, f the Michigan Board of Land Surveyors or by	, 4 and 5 above were in			_ - 7_	-1	+	-{ 5	-14	-	-13-				
Law; established, re-establish	ned, monumented, re-monumented, recovere	ed, found as expressed	<u>'</u>	1 1	_	1-1	\top	1		+	1				
below:		•	9	9	20 	1 21	\top	-55	23		-24- 				
A. Description of original m	nonument and accessories and/or subsec				29	-21	丰	-27	26		25				
Set post in 1816 G.L.O.		. 1	¹├-	┼╌┼		╂╾┼			╂╌┼	_	+				
There is one LCRC reco	orded at Oakland County; Albright 1972.	•	2	31	3 2	 3 4	+	-34	35	+	-3 6 -				
B. Description of corner ev reestablishing corner:	idence found and/or method applied in re	estoring or	3 L	1 1		.li.					-				
Springfield Township. To located near this position concrete monument plants.	nonument with remonumentation cap #22 The monument as found is 245.60' south n, one being 17.55' west and 9.74' south ced by Mr. Ward. John Albright's LCRC a	of Springfield Townshi and the other being 0. as recorded in L 6716 f	p's / 39' é P 74	A-4. east : 4 sta	Two and 1 ates t	iron 109.9 hat N	pipe:)5' no /i-4 is	s we orth o s 245	re al of this 5.85'	50 S					

south of A-4 Springfield Township. The dossler for A-4 Springfield Township includes surveys by both Mr. Ward and Albright using both A-4 of Springfield Township and M-4 of Rose Township.

Recovered Witness:

S 27°E 69.59' PK nall with Grant Ward washer west side 18" Oak.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Recovered Oakland County Remonumentation Brass Cap stamped #22445.

Set Witnesses:

S 08°E 71.82' Mag nail with OCRT #22445 east side 18" Oak. S 27°E 69.59' Mag nail with OCRT #22445 west side 18" Oak. S 02°E 92.20' Mag nail with OCRT #22445 west side 18" Oak. N 70°W 217.35' chiseled "+" on south bolt of high tension line tower. N 01°44'03"W 245.60' A-4 Springfield Township monument with OCRT #22445.



Surveyor's Michigan License No. _