## LISER 15709rc017

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Oakland Located In: Corne	r Code #
1. Public Land Survey T 4N R 9E H	-13
T R	Compliance with ACT 345, P.A. 1990
T R	APPROVED ON: 9-27-95 10m
	OAKLAND COUNTY REMONUMENTATION PERR GROUP COMMITTEE
3. Miscellaneous       S T R	Register of Deeds Stamp & File Number
Lot No, Recorded Plat      Private Claims	<u> </u>
5. Thate classes	2 - 6 - 5 - 4 - 3 - 2 - 1 - 1
	4 7 8 9 10 11 12
I, James J. Scharl , in a field survey on 8-24	, 19_95
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found	
as expressed below:  NOTE: Not more than 4 corners, all in the same town and range, may be	
on this certificate.	$\begin{array}{c ccccccccccccccccccccccccccccccccccc$
A. Description of original monument and accessories and/or subseq	
Post set in 1817 G.L.O. survey.	
N 25°E 2 1ks 8" W Oak S 27°E 40 1ks 18" B Oak	
5 27 B 40 183 10 B 688	\$ 7.00 MISCELLANEOUS RECORDING \$ 2.00 REHONUMENTATION 29 SEP 95 7:29 A.M. RECEIPT# 3B
	PAID RECORDED - OAKLAND COUNTY LYNN D. ALLEN, CLERK/REGISTER OF DEEDS
B. Description of comer evidence found and/or method applied in restoring or reestablishing corner:	
Corner at this location was obliterated. Relocated corner from measurements shown on the "Oakland Ridge Subdivision", L 18, P 34, O.C. Records, and the "Woodhull Lake Subdivision", L 38, P 27, O.C. Records.	
	JAMES J. SCHARL
	PROFESSIONAL SURVEYOR SURVEYOR SURVEYOR
	MANGEO LAND SUFF
C. Description of monument for corner and accessories established	to perpetuate locating the position of the corner:
Set concrete monument with 0.C. remonumentation	brass cap. $\eta.60$
N 10°W 39.10' SE corner House #4539 N 05°E 10.97' NW corner House #4533 West 3.78' PK/remon tag S face 28" Oak	2.0 <sup>c</sup> Qr
S 50°W 25.12' PK/remon tag S face twin 16" Oak The selected location is a careful and faithful reestablishment of the position of the original corner. This corner was also accepted by the Oakland County Peer Group as established under Act 345 of P.A. 1990.	
Signed by Wall	Date <u>Sept. 26, 1995</u>
Surveyor's Michigan License No. 19843	FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971