SURVEY & REMONUMENTATION

960m105

MAY - 1 1995

LAND CORNER RECORDATION CERTIFICATE

94 242435

For corners in	COMMISSION
. 0. 00	6 8 8 8 8 8 8 8 8 8 8

Oakland

1. Public Land Survey

2. Property Controlling

Miscellaneous

Property in Sec.

in Section

Filing Requirement of Act 74, Mich. P.A. 1970

B-3

Corner Code ##

1970	OK -	T. EMI	
	REHONUNE		i
			EIPT# 134B
PAID			KLAND COUNTY
LAMM I). ALLEN, C	LERK/REGIS	ier of deeds
	ACT	npliance with 345, P.A. 199	•
A IDDD	OVED ON:	1-5-	94
Regista	MULTER	SYAMPHADIF OUP COMM	

__ , Recorded Plat __ 5 Private Claims

Located In:

Т

_ T _

S

S.

S

T 4 N R 10 E

__ R _

_ R

___ R _

R

T R R _ R .

Orion


Township

Huston K. Kennedy, in a field survey on , 19 <u>93</u> November 9 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

1817-GLO Wampler, D.S.; Set Post; 24" Black Oak N69°E 35 Lnks 1979-Jones, P.S. #16045; LCRC L.7466, Pg.144 - Fnd 1/2" Iron Rod



- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - 1993 Kennedy Surveying, Inc. Kennedy, P.S. #17623 Fnd a concrete monument in a fence line extending East and West There is a fence line 20' ± West of the corner extending to the South.

The witness trees are still existing, but the witness points were grown over.

I accepted the found concrete monument as the best evidence of the original corner position.

- Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - I placed a 2" diameter cap stamped Oakland County Remonumentation P.S. #17623 on the found concrete monument.

NO5°E-13.15 ft-Set PK & Remon. Washer East face 28" Oak N45°W-15.38 ft-Set PK & Remon. Washer NE face 15" Oak S63°W-20.56 ft-Set PK & Remon. Washer North face 16" Oak S50°E-34.90 ft-Set PK & Remon. Washer SW face 10" Oak

The selected location is accepted by me and is generally accepted by to as the best available evidence of the position of the original position

Signed by

Date June 22, 1994

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS

WHINKHHIMINING THE

LE OF MICHIE

Very Harman

Surveyor's Michigan License No.