## UBER 19758 PG 475



LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 LIBER 19758 PAGE 475
47.00 MISC RECORDING
42.00 REMONUMENTATION
03/30/1999 01:03:22 P.M. RECEIPT# 12968
PAID RECORDED OBALLAND COUNTY
PAID RECORDED OF CHERK/REGISTER OF DE For corners in Corner Code # Located in: G. WILLIAM CADDELL, CLERK/REGISTER OF DEEDS <u>Oakland</u> (County) G - 12T<u>5N</u> R<u>8E</u> 1. Public Land Survey SURVEY & Compliance with ACT 345, P.A. 1990 MOTATE RFI 1-27-98 55 APPROVED ON: R OAKLAND COUNTY REMONUMENTATIO 2. Property Controlling <del>MAR 2</del> 1 2000 PEER GROUP COMMITTEE in Section Register of Deeds Stamp & File Number 3. Miscellaneous Property in Sec. SECTION , Recorded Plat 4. Lot No. 5. Private Claims I Timothy J. Hart in a field survey on 5-23 , 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in 5 requirements of F.A. 74, interingal F.A. of 1970, the content points then the current manual of survey instructions of the conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate. A: Description of original monument and accessories and/or subsequent restoration: Post set in 1823 G.L.O. survey; 14" W. Oak N 53°W 61 1ks; 16" B. Oak S 33°E 63 1ks. A) LCRC, L6002, P518, Albright, 1972 (1) B) Survey, L6851, P712, Carlson, 1977 (1) C) Survey, unrecorded, Newman, 1988 (2) D) Survey, unrecorded, Dekeyser, 1996 (4) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Recovered 5/8" square iron located on the N'ly extension of Wildwood Road. Recovered 5/8" square 1100 located on the 13/8" rerod was recovered 33 ft east of the rows run east and west from the corner. A 3/8" rerod was recovered 33 ft east of the STEE OF MICHIE corner. Witnesses Recovered North 15.60' Nail/tag 22445 W. 12" Oak (C,D) S. 14" Oak (A,B,C) \* . J. HART Nove 4.44 Nail/tag 22445 N. 8 Hickory (D)

S 05°W 4.22' Nail/tag 22445 W. 6" Ash (D)

West 11.90' Nail/tag 22445 S. 8" Oak (D)

Description of monument for corner and accessories established to perpetuate locating the position of the corner.

Set concrete monument w/O.C. remonumentation brass cap, replacing 5/8" square iron 41.26' Nail tag 4.44' Nail/tag 22445 N. 8" Hickory (D) PROFESSION! N 70°E N 80°E SURVEYOR C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: State Plane Coordinates: 15.25' PK/remon tag E. 12" Oak N 473180.1898 North 4.35' PK/remon tag N. 8" Hickory E 13353384.3997 N 80°E 4.15' PK/remon tag W. 6" Ash S 05°W 11.81' PK/remon tag N. 8" Oak The selected location is accepted by the Contractor and is generally accepted by professional surveyors as the best available evidence of the position of the original corner. This corner was also accepted by the Oakland County Peer Group as established under Act 345 of P.A. 1990 Date\_\_ Honott Signed by 33136 Surveyor's Michigan License No.