隊 海滨

PATRITIMENTON

## LAND CORNER RECORDATION CERTIFICATES 7.00 MISCELLANEOUS RECORDING Filling Requirement of Act 74, Mich. P.A. 1970\$ 2.00 REMINIMENTATION 14 JUL 95 8:40 A.M. RECEIPT

For corners in		on to Act 14, Wildis, P.		95 8:40 A.H.	
Oakland (County)	Located in:Oxford Twp	Corner Code #	ı PAID		RECEIPT# 9B - OAKLAND COUNT)
(County)					REGISTER OF DEEDS
			Citat Da	HELLIST DECKET	ventages of preof
Public Land Survey	T <u>5N</u> R <u>10E</u>	<u>M-11</u>			
	<u>T</u> <u>R</u>				_
	T R			Compliance w ACT 345, P.A.	
0. 5	T B				
2. Property Controlling	S T B		APPROVE	D ON:	-95 Tans
in Section	ST R		UAKLANE PE	COUNTY REMO ER GROUP COM	DNUMENTATION
3. Miscellaneous	ST R				
Property in Section	S T R		Register o	of Deeds Stamp	& File Number
A Let No	December of Block				
5. Private Claims	Recorded Plat			BCDEF	<u>G HIJK</u>
5. Flivate Ciains		<u> </u>			
			ياً		
Huston K. Kenneda	, in a field survey onApril	25	4	-789-	10-11-1-
do hereby certify that under re-	quirements of P.A. 74, Michigan P.A. of	<u> 2b</u> , 19 <u>95</u>	, 5	<del>                                     </del>	
in lines 1 and 2 above were in	conformance with regulations and rules	therefore as required in the c	urrent 6	1817	15-1-14-
manual of survey instruction	ns of the United States Department	of the Interior, Bureau of	Land 7		<del>                                     </del>
<ul> <li>Management or by a decree or</li> </ul>	of a Court of Law and/or that the comer	points mentioned in lines 3.	4 and 8-	192021-	22
5 above were in conformance	with the rules of the Michigan Board	of Professional Surveyors or	rbya <sub>9</sub> _		
as expressed below:	ablished, re-established, monumented, a	re-monumented, recovered,	found 10	30 29 28	27 26
•		_	11		
NOTE: Not more than 4 co on this certificate.	omers, all in the same town and rang	ge, may be recorded	f		
on the occumulate.			12 13	31 32 33-	34 35 3
2.) 1977-Kennedy, PS #17 3.) 1986-Kennedy, PS #17 4.) 1977-Kennedy, PS #17 5.) 1977-Kennedy, PS #17 6.) 1979-Kennedy, PS #17 7.) 1985-Kennedy, PS #17 8.) 1985-Kennedy, PS #17 9.) 1991-Kennedy, PS #17 B. Description of corner of 1995 Kennedy Surveying, 1	5 #10868; LCRC L.6260, Pg.558 - Fn 7623; LCRC L.6965, Pg.93 - Fnd 1/2 7623; LCRC L.9248, Pg.637 - Fnd 1/2 7623; Unrecorded Survey - Fnd 1/2 76	" Iron Rod 2" Iron Rod 1/2" Iron Rod, used same Iron Rod, used same wit Iron Rod feet South Iron Rod feet South Iron Rod feet South Iron Rod Second 1/2" Iron Rod 31, T5W, R11E, Iron Rod verify the location o	as 1977 LCRC as 1977 LCRC as 1986 LCRC as 1986 LCRC as 1986 LCRC ablishing corner of the centerling remains and extending LCRC addison Twp. (1) f the found 1/2	: ne of Drahner R ng to the North feet West of co M-11).	which has a succe
FIELD HEASUREMENTS I	35. <u>18</u> .				7 go (r
M-11 to M-10 2656.60 M-11 to A-11 (Addiso	5 Ft., GLO = 40 chains or 2640.00 0 Ft., GLO = 40 chains or 2640.00 on Twp.) GLO = 4 links or 2.64 Ft. ent for corner and accessories esta	Pt.	cating the positi	on of the come	ы: Д- <sup>3</sup> -00,
M-11 I replaced the found	d 1/2" Iron Rod with a 5/8" x 24"	Iron Rod W/2" diameter	hrass can staum	ad Sakland Coun	tu Pamanumantatia
19 \$1/0%;			our bough	vostana wan	-1 weatherstruction
S11 E 18.12' Set PK	& Remon. Washer NE face clump of	Cherry			
S63 W 26.15' Set PK	& Remon. Washer NW face 22" Oak				
mos & 93.9/' Set PK H48 W 57.83' Set PK	& Remon. Washer NW face Power Pol & Remon. Washer SW face $18^{\rm M}$ & $26^{\rm M}$	e I tuin Osk			
			•	· · · · · · · · · · · · · · · · · · ·	Militina.
The selected location is	accepted by me and is generally a	accepted by Professional	. Survevors as t	he best awalling	bliston
position of the original	corner.			J. A. T.	Secretary Continue
				\$ 5° /	<b>HUSTON</b>
/ / //	A Port	•		PR	
	M1 < X	_	.Tsm = 1#	100mm - 1 ''	KENNEDY COPESSIONAL
Signed by	16	Date	June 15,	TAAR	SURVEYOR
Surveyor's Michigan Licens	se No. 17623	FORM APP	PROVED BY MICHIGAN STATI	E BOARD OF THE BOOM	L SURVEYORS, JAM 25 CETT
7				· Marco po	OCCOMPANY NEW YORK
•					N.522101144