Oceana County Remonumentation STATE OF MICHIGAN COUNTY OF OCCANA RECEIVED FOR PEOCRO Peer Group Reviewed & Approved FFB 2 2 1996 5125-95 COMMISSION 124 LAND CORNER RECORDATION CERTIFICATE J. Randolph Hepworth Oceana County Surveyor JUL 10 P2:47 Filing Requirement of Act 74, Mich. P.A. 1970 For corners in County Oceana Located In: Corner Code ## REGISTER OF DEEDS Public Land Survey T_13_R_18_ T ____ R __ R **Property Controlling** T R ____ T ____ R _ in Section ___ T ____ R _ Miscellaneous Register of Deeds Stamp & File Number Property in Sec. Lot No. _ , Recorded Plat _ Private Claims _

10 11

100629

E. Williams

Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

G-8 1/4 Corner Common to Sections 21 and 22

T13N, R18W CLAYBANKS TOWNSHIP

GLO SET POST 12" Sugar For 1/4 post

I.J. Randolph Hapworth . in a field survey on June 12

Book A, Pg 128; S. Edson, 1882;

on this certificate.

expressed below:

Corner not described or witnessed.

Book A, Pg 138; S. Edson, 1883;

10" B. Oak N43°W 26lks "Old original stake always kept up in the roots of a witness tree (Maple)"

8" B. Oak N46°E 13 1/2lks

Pole N30°E 53.30

2' N of c/l of road on brush row to north and on West edge of woods to

south, also found 1/8 post to west which fell on line and 1/2 way between G-8 & F-8

22" Oak N60°W 59.75

28" Oak S10°E 42.0

Act 132 survey; Hackbardt, PS25844, 2-4-84; same same as above

LCRC 100313, Hackbardt, PS25844, 2-4-84; Found T Iron

witnesses same as LCRC 100313

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner

I found an old T-shaped fence post, 6" below gravel surface, in the center of an east-west gravel road and on an old fence (lying down) to the south & on a Maple tree line to the south. A wide Sassafras tree occupation line runs north m/l from the corner. All witnesses for LCRC100313 are standing and measure good.

Upon excavation and removal of the T-Fence post, it was found to be 4.5 feet long.

Further search of the area failed to yield any other evidence for a conflicting position for the corner. This represents the best available evidence for the position of the corner. The Found T-Fence Post is accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

G-8 1/4 Corner Common to Sections 21 and 22 T13N, R18W CLAYBANKS TOWNSHIP Set "COUNTY SURVEYOR" HARRISON 4"X20" cast iron Monument above the found T-Fence Post which was driven down. MAG nail NE Face Power Pole 312°az 66.77 EDM 60d spk NE Face 28" Oak 296°az 59.52 **EDM** SE Face 20d spk Power Poie 33°az 53.49 **EDM** NE Face 16" Hemlock 60d spk 123°az 85.93 FDM SW Face 60d spk 48" Oak 147°az 48.17 **EDM** 60d spk E Face 24" Oak- dead 169°az 43.25 **EDM**

Signed by Surveyor's Michigan License No. .

Date

TICHIBAN STATE POAND OLLAND SUN

ON LAND SURVEYERS, JAN. 28. 1971

REVISED JAN., 1983

I. RANDOLPH