## LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

called this the S 1/4 Cor. of S-35, T16N-R18W, and recorded it as J-13.	FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	
3. MSCELLANDOUS PROPERTY IN SECTION 1. S. R. L. L. S. R. L. L. L. L. S. R. L. L. L. S. R. L.	1. PUBLIC LAND SURVEY	T 15 N. R 18 W	J-1; J-3	
3. MSCELLANDOUS PROPERTY IN SECTION 1. S. R. L. L. S. R. L. L. L. L. S. R. L. L. L. S. R. L.	2. PROPERTY CONTROLL-	N. E	·   •	
A LOT NO				
The corner points mentioned in lines 1 and 2 above were, in a field survey onAug29				
Carl F. Roser	5. PRIVATE CLAIMS			
B. (continued) Sec. 2 per original Govt. Survey.  B. Description of corner evidence found and or method applied in restoring or re-establishing corner: Fd. 3/4" pipe & accepted as N 1/4 Cor. S-2, T15N-R18N. Note: S.Barnett erroneously called this the S 1/4 Cor. of S-35, T16N-R18N, and recorded it as J-13.  Re-estab. 1/4 Cor. to Sec!s. 2 & 11, equidistant & on line between Sec. Cor's to E & M. This fits U.S. (G.L.O.) distance very reasonably. Note: first attempted to restore Co by occupancy. Tied up most of 40 Ac. Cor's. in Sec's. 2 & 11. Just will not lead you to acceptable 1/4 Cor. position. Stover used fn. Cor. post, fn. N-E-W (we fd. 3/4" pipe) for ctr. of Sec. 11; a line across the Comp. (S.P.) S 1/4 S-W (in lake) and Stov (fn.Cor.) ctr. projects to rd. Ctr. to South (at approx. N 1/4 S-W) or 64'+ E. of our N 1/4 Sec. W. Just could not accept this rd.intersection as proper position for 5 1/4 C. Description of monument for corner and accessories established to perpetuate locating the position of the corner (continu J-1  Fd. 3/4" pipe; added DNR Mon. & Ced. Post Set 5/8"X40" Rod w/RLS Cap. (buried) 16" Ash S75°E 19.3 Power Pole S65°E 106.68 15" R. Oak S50°W 3.0 NE'1y Corr. Conc. Dr. S09°E 168.9 S 1/4 35 T16N-R18W N87°53'W 26.40 Ctr. N-S Gr.Rd. Due E 64' N-S Rd. (old R.R. Grade) Ctr. E-W Gr.Rd. Due E 64' N-S Rd. (old R.R. Grade) Ctr. E-W Gr.Rd. Due E 64' N-S Rd. (old R.R. Grade) Ctr. E-W Gr.Rd. Due N 7' Due W 48'+ Set Ced. Post w/Loc. Tag Due N 33'  SIGNED BY DATE STATE AND UNITED STATES AGENCIES:  SIGNED BY DATE STATES AGENCIES:  SIGNED BY DATE STATES AGENCIES:  SIGNED BY DATE STATES AGENCIES STATES AGENCIES STATES AGENCIES STATES AGENCIES STATES AGENCIES STATES AGE	the corner points mentioned in l re-established, monumented, re- and rules therefore as required Bureau of Land Management or and 5 above were, in a field surv as expressed below and in confo	ines 1 and 2 above were, in monumented, recovered or in the current manual of sur by a decree of a court of la- ey on	a field survey onAug. 29 restored as expressed below and vey instructions of the United Sw. Furthermore, that the corner, 19, found, recovered, res	, 19.78., established, d in conformance with regulations States Department of the Interior, or points mentioned in lines 3, 4 stored, established or re-established
B. Description of corner evidence found and or method applied in restoring or re-establishing corner:  Fd. 3/4" pipe & accepted as N 1/4 Cor. S-2, T15N-R18N. Note: S. Barnett erroneously called this the S 1/4 Cor. of S-35, T16N-R18W, and recorded it as J-15.  Re-estab. 1/4 Cor. to Sec's. 2 & 11, equidistant & on line between Sec. Cor's to E & M This fits U.S. (G.L.O.) distance very reasonably. Note: first attempted to restore Co by occupancy. Tied up most of 40 Ac. Cor's. in Sec's. 2 & 11. Just will not lead you to acceptable 1/4 Cor. position. Stover used fn. Cor. post, fn. N-E-W (we fd. 3/4" pipe) for ctr. of Sec. 11; a line across the Comp. (S.P.) S 1/4 S-W (in lake) and Stow (fn.Cor.) ctr. projects to rd. Ctr. to South (at approx. N 1/4 S-W) or 64'* E. of our N 1/4 Sec. W. Just could not accept this rd. intersection as proper position for 5 1/4 C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: (continu J-1  Fd. 3/4" pipe; added DNR Mon. & Ced.Post Set 5/8"X40" Rod W/RLS Cap. (buried) 16" Ash S75'E 19.3 Power Pole S65'E 106.68 15" R. Oak S50'W 3.0 NE'ly Cor.Conc.Dr.S09'E 168.9 S 1/4 35 T16N-R18W N87*53'W 26.40 Ctr. N-S Gr.Rd. Due E 64' N-S Rd. (old R.R. Grade) Ctr. E-W Gr.Rd. Due N 7' Due W 48'* Set Ced.Post W/Loc.Tag Due N 33'  SIGNED BY CHIEFOR SUMMERANTY DATE  APPROVED AND SIGNED BY DATE  CHIEFOR SUMMERANT PARTY DATE  APPROVED AND SIGNED BY DATE  CHIEFOR SUMMERANT PARTY DATE  MICHIGAN REGISTRATION NO. 12028  DATE  SURNEYORS MICHIGAN REGISTRATION NO. 12028  FOR STATE AND UNITED STATES AGENCIES:  SIGNED BY DATE  CHIEFOR SUMMERANT PARTY DATE  APPROVED AND SIGNED BY DATE  CHIEFOR SUMMERANT PARTY DATE  APPROVED AND SIGNED BY CHIEFOR BURNEYOR DATE  GOLDEN TOWNSHIP	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	ĸĸĸĸĸĸĸĸĸĸĸĸĸĸĸĸĸĸĸĸĸĸĸĸĸĸĸĸĸĸĸĸĸĸĸĸĸĸĸ	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	
Fd. 3/4" pipe & accepted as N 1/4 Cor. S-2, T15N-R18N. Note: S.Barnett erroneously called this the S 1/4 Cor. of S-35, T16N-R18W, and recorded it as J-13.  Re-estab. 1/4 Cor. to Sec's. 2 & 11, equidistant & on line between Sec. Cor's to E & W This fits U.S. (G.L.O.) distance very reasonably. Note: first attempted to restore Co by occupancy. Tied up most of 40 Ac. Cor's. in Sec's. 2 & 11. Just will not lead you to acceptable 1/4 Cor. position. Stover used fn. Cor. post, fn. N-E-W (we fd. 3/4" pipe) for ctr. of Sec. 11; a line across the Comp. (S.P.) S 1/4 S-# (in lake) and Stov (fn.Cor.) ctr. projects to rd. Ctr. to South (at approx. N 1/4 S-#) or 64'+ E. of our N 1/4 Sec. #/. Just could not accept this rd. intersection as proper position for 5 1/4  C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. (continu J-3  Fd. 3/4" pipe; added DNR Mon.& Ced.Post Set 5/8"X40" Rod W/RLS Cap. (buried) 16" Ash S75°E 19.3 Power Pole S65°E 106.68 15" R. Oak S50°W 3.0 NE'ly Cor.Conc.Dr.S09°E 168.9 S 1/4 35 T16N-R18W N87°55'W 26.40 Ctr. N-S Gr.Rd. Due E 64' N-S Rd. (old R.R. Grade) Ctr. E-W Gr.Rd. Due E 64' N-S Rd. (old R.R. Grade) Ctr. E-W Gr.Rd. Due N 7' Due W 48'+ Set Ced.Post w/Loc.Tag Due N 33'  SIGNED BY CARL F. ROSER LAND  SURVEYOR'S MICHIGAN REGISTRATION NO. 12028  FOR STATE AND UNITED STATES AGENCIES:  SIGNED BY CARL F. ROSER LAND  APPROVED AND SIGNED BY DATE  SURVEYOR'S MICHIGAN REGISTRATION NO. 12028  GOLDEN TOWNSHIP	B. (continued) Sec.	2 per original Govt.	Survey.	
SURVEYOR'S MICHIGAN REGISTRATION NO. 12028  FOR STATE AND UNITED STATES AGENCIES:  SIGNED BY DATE DATE DATE DATE 12028  MICHIGAN REGISTERED LAND SURVEYOR	Fd. 3/4" pipe & acc called this the S 1 Re-estab. 1/4 Cor. This fits U.S. (G.L by occupancy. Tied to acceptable 1/4 C pipe) for ctr. of S (fn.Cor.) ctr. proj N 1/4 Sec. //. Just C. Description of monument for Fd. 3/4" pip 16" Ash 15" R. Oak S 1/4 35 T16	epted as N 1/4 Cor.  /4 Cor. of S-35, T16  to Sec's. 2 & 11, eq.  .0.) distance very r  up most of 40 Ac. Cor. position. Stove ec. 11; a line acros ects to rd. Ctr. to could not accept this r corner and accessories esta  J-1 e; added DNR Mon. & C  S75°E  S50°W N-R18W N87°53'W	S-2, T15N-R18N. Note: N-R18W, and recorded i uidistant & on line be easonably. Note: firs or's. in Sec's. 2 & 11 or used fn. Cor. post, s the Comp. (S.P.) S 1 South (at approx. N 1/s rd.intersection as published to perpetuate locating the ded.Post Set 5/8"X40 Power Pole 3.0 NE'ly Cor.C Ctr. N-S Gr	S.Barnett erroneously t as J-13. tween Sec. Cor's to E & W t attempted to restore Cor. Just will not lead you fn. N-E-W (we fd. 3/4" /4 S-# (in lake) and Stove 4 S-#) or 64'+ E. of our Stove roper position for \$ 1/4 e position of the corner: (continue J-3 " Rod w/RLS Cap. (buried) S65°E 106.68 onc.Dr.S09°E 168.9 .Rd. Due E 64' .Rd. Due N 7' t w/Loc.Tag
FOR STATE AND UNITED STATES AGENCIES:  SIGNED BY		•		anninn,
FOR STATE AND UNITED STATES AGENCIES:  SIGNED BY	SURVEYOR'S MICHIGAN RE	GISTRATION NO. 12	028	OF MICKING
GOLDEN TOWNSHIP	FOR STATE AND UNITED S	TATES AGENCIES:		G CARL Z F. ROSER
GOLDEN TOWNSHIP	SIGNED BY	CHIEF OF SURVEY PARTY	DATE	SURVEYOR NO.
	APPROVED AND SIGNED BY	MICHIGAN REGISTERED	DATE	12028 LAND SURILLIE