ceana County Remonumentation FEB 2 5 1994 er Group Reviewed & Approved 11-18-93 100531COUNTY REMONUMENTATION OCEANA Randolph Hepworth LAND CORNER RECORDATION CERTIFICATE STATE OF MICHIGAN ceana County Surveyor Filing Requirement of Act 74, Mich. P.A. 1970 COUNTY OF COLARA RECEIVED FOR PEOGRD or corners in OCEANA Located in: Corner Code ## intvi DEC 14 A10:25 T 15N R _ 16W Public Land Survey A-7R R E mertino T .. R REGISTER OF DEEDS **Property Controlling** Ţ __ R ... in Section S Т R Miscellaneous S Τ. _ R Register of Deeds Stamp & File Number Property in Sec. S T R _ , Recorded Plat Private Claims _ J. Randolph Hepworth November 22, 1993 in a field survey on o hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned I lines 1 and 2 above were in conformance with regulations and rules therefore as required in the urrent manual of survey instructions of the United States Department of the Interior, Bureau of Land lanagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 bove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a ourt of Law; established, re-established, monumented, re-monumented, recovered, found as xpressed below: 10 OTE: Not more than 4 corners, all in the same town and range, may be recorded 11 on this certificate. 12 Description of original monument and accessories and/or subsequent restoration: A. A-7 CORNER COMMON TO SEC 18 & 19 E GLO 18" SUGAR FOR CORNER NO WITNESSES ELBRIDGE TWP T15N, R16W BOOK A-51 S. EDSON, JUNE 1879 BOOK A-80 S EDSON, 1880 W BOOK A-216 EM HYDE, DEC 1888 ROUGH LIMESTONE 18" LONG W/ SEAMS IN DIFFERENT DIRECTIONS WHITE LIMESTONE 17"X16"X6" SEAMS IN DIFFERENT DIRECTIONS
88 SAME AS BOOK A-80 OCRC, 1947: PLOW POINT & IRON ROD 20" MAPLE N45°E 93.0 24" MAPLE N55°E 23.0 S60°E 84.0 APPLE S45°W 98.0 CONSUMERS POWER CO.; G. BLASS, 1967 FD IRON ROD 20" MAPLE N45"E 93.00 24 24" MAPLE N55°E 93.00 P POLE S60°E 84.00 APPLE S45°W HEPWORTH, PS26457, 10-24-81 FOUND 1" PIPE 28" MAPLE N55°E HEPWORTH, PS26457, 9-7-90; SET 1/2"X2" IRON AT BLASS POSITION PERPETUATION TEL POLE 316°AZ 40.68 151°AZ 63.19 RD NAME SIGN 232°AZ 62.84 PP/TRANSF P POLE 17°AZ 127.26 B.Description of corner evidence found and/or method applied in restoring or reestablishing corner This Iron fits one Blass witness (24" Maple N55°E 93.00") and the distance south to the Found the 1/2"x2' Iron by Hepworth, 9-7-90. ction corner. Upon removal of this Iron and excavation, I discovered that below the Hepworth Iron at a depth of 30" below road exement is a 1" pipe that is beside and about 4" higher than an old Plow Point which is about 1/2"x4"x?length. I believe this corner Section comer. I believe this comer to be the 1947 OCRC monument that was later found by Blass in 1967. This corner is in the centerline intersection of the east-west pavement, gravel road to south and center of Dirt Track to North. No excavation below this plow point was believed necessary to further confirm this corner location. THIS CORNER IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORGINAL CORNER. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. A-7 CORNER COMMON TO SEC 18 & 19 ELBRIDGE TWP T15N, R16W AND SEC. 13 & 24, T15N, R17W SET "COUNTY SURVEYOR" HARRISON 4"X20" CAST IRON MONUMENT IN PLACE OF FOUND 1/2" IRON AND ABOVE THE 1" PIPE & Ea Ch Change PLOW POINT. C/L E-W PAVEMENT, C/L GRAVEL TO SOUTH, C/L DIRT TRACK TO NORTH POWER POLE/TRANSF. POWER POLE/TRANSF TE OF MUNO 60d SPK SW FACE S33°E 63.50 **EDM** PK NAIL W FACE N13°E 127.22 **EDM** 60d SPK NE FACE TELEPHONE POLE N44°W 40.65 **EDM** J. RANDOLPH SE FACE 60d SPK 30" MAPLE

N61°E

Date

Sypwort

26457

Signed by .

Surveyor's Michigan License No.

94.00

November 24

EDM

FORM APPROVED BY MICHIGAN SATE BOARD OF LAND CORVEYORS, JA 2645 PEVISED AND LAND SEVISED AN

HEPWORTH

LAND 99 SURVEYOR

2645 FVISED NAV. 14