LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY	T. 27 N. R. 1 E.	D-6; E-8	
2. PROPERTY CONTROLL- 2: ING IN SECTION—	0 ,T. 27 N. R. 1 E.	16	
3. MISCELLANEOUS PROPERTY IN SECTION		1	·
4. LOT NO, REC	CORDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
the corner points mentioned in re-established, monumented, re and rules therefore as required Bureau of Land Management of and 5 coope were, in a field sur	lines 1 and 2 above were, in a -monumented, recovered or r in the current manual of surv r by a decree of a court of law yev on	estored as expressed below and rey instructions of the United Structure, that the corner, 19, found, recovered, rest	of P.A. 74, Michigan P.A. of 1970, 7, 1983, established, in conformance with regulations tates Department of the Interior, repoints mentioned in lines 3, 4 ored, established or re-established ration for Land Surveyors or, by a
жжижжжжжжжжж жжижжжжжжж daunitnod . o	ХХИК ХИККИММОХХИК ХЬББ	ХОНИЮХХ ХИИДЭННЖ	
SET TWIN	16 5/8" ROD WITH RLS 9" RED OAK N3 14" RED OAK S3		
E-8 - SET CORNER BY S FOUND A PIPE BY ERENT SECTION C CORNER WOULD GR AND DID NOT FEE POSITION. 16 - SET CORNER BY S	TION OF THE TRUE INGLE PROPORTIONA SEELEY 51' NW WH ORNER LOCATIONS, EATLY DISTORT THE L JUSTIFIED IN ACT TANDARD SURVEY PR or corner and accessories estal	1/4 LINES. TE MEASUREMENT BETWICH APPARENTLY WAS OR ELSE SET GROSSLY SUBDIVISION OF BOTCEPTING WHAT IS FELOCEDURE FOR THE SUBDISHED to perpetuate locating the	WEEN SECTION CORNERS. SET RELATIVE TO DIIF IN ERROR. SEELEY TH SECTIONS 20 AND 21 TO BE AN ERRONEOUS BDIVISION OF SECTIONS Exposition of the corner:
			SILLING OF MICH
SIGNED BY Lun	ith Josthin	DATE 10	J. ØSTLING Z
SURVEYOR'S MICHIGAN RI	EGISTRATION NO. 10	<u>068</u>	40068 . O.
SIGNED BY	CHIEF OF SURVEY PARTY	DATE	(SEAL)
APPROVED AND SIGNED F	MICHIGAN REGISTERED	LAND BURVEYOR	(SEAL)
SURVEYOR'S MICHIGAN R	EGISTRATION NO	osc	CODA COUNTY