## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For comers in Located in: Comer Code # Oscoda (County) M-2) T 27NR 3E 1. Public Land Survey Sec. Sec. T<u>27N</u> R<u>4E</u> R R 2. Property Controlling A R S т in Section S 3. Miscellaneous S Т H Property in Sec. , Recorded Plat 4. Lot No. 5. Private Claims

Liber 4 pg 291

STATE OF MICHIGAN DSCODA COUNTY FILED

24 SEP 98 11:14 A.M.

PATSY J. PETERS REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, Marvin E. Myers, in a field survey on <u>2 February</u>, 19<u>98</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.


A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. May 1839 Lewis Clason D.S. Mon: Post

Wit:20" Herniock S34°W 20 links 24" Hemlock N19°W 16 links

Norman C. Caldwell, R.L.S. Aug 22, 1966 (unrecorded Harry Dew survey)

Norman C. Caldwell, R.L.S. #12018 May 10, 1973 (Unrecorded Dwight Handrich Survey Mon - Found record ¾" bar and replaced with Standard Oscoda County Comer Monument Wit: Telephone Marker Post 880°W 27.5 P. Pole N45W 79.8 16" Balsam N25°W 104.9



Larry G. Beauregard L.S. #18654 L.3, P. 390 Aug 31, 1983 Mon: Existing Standard County Comer Wit: Telephone Marker Post S80°W 27.5' Power Pole N45°W 79.8°

- Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found Standard County Corner in centerline of North, South Road and centerline Road to East. Found Power Pole N53°W 79.89'
- Description of monument for comer and accessories established to perpetuate locating the position of the comer:

1/4 Cor. Sec. 1, T27N, R3E and Sec. 6, T27N, R4E Mon: Standard County Corner monument in place. Set Spike in South Side 16' White Pine S68°E 69.28' Wit Set Spike in South Side 13" Balsam N61°E 60.65" Set Spike in South side Power Pole N53°W 79.89' Set Spike in North side 8" Balsam N90°W 73.68"

Accepted as the best available evidence of the position of the Original Comer.

## APPROVED

County Remonumentation Peer Review Group NCC 45EPT 98



Signed by Mon & Man	
Surveyor's Michigan License No. 31600	
Surveyors Michigan Hoanse No. 31600	

August 25, 1998

REMONUMENTATION

Form approved by Michigan State Board of Professional Surveyors, Jan. 29, 1971 Revised May 14, 1973 Revised Jan., 1983 Revised Oct., 1985

NOV 0 3 1998

SURVEY &