## SURVEY & REMONUMENTATION

APR 2 4 1995

For corners in

4. Lot No. 5. Private Claims \_

## OTTAWA COUNTY REMONUMENTATION

## RECORDED

COMMISSION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

QLIDEC 15 AKII: 51

Dhy air Bedinan REGISTER OF DEEDS OTTAWA COUNTY. MI

	Ottawa (County)	Located In: Jamestown Township	Corner Code ##
1.	Public Land Survey	T <u>5N</u> R <u>13W</u> T R	C-9
		T R T R	
2.	Property Controlling in Section	S T R S T R	
3.	Miscellaneous Property in Sec.	S T R S T R	

\_ , Recorded Plat \_

Register of Deeds Stamp & File Number

1. Rodney D. Unema , in a field survey on \_ Dec. 8 , 19 94 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5

above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10 11 12

A. Description of original monument and accessories and/or subsequent restoration:

C-9 Corner Common to Sections 19, 20, 29 and 30 Original gov't corner set in Dec. 1831 by Sylvester Sibley Set post Beech 12" N52°E 20 links Beech 10" S55°W 15 links

L.C.R.C. Liber 2, Pg. 33 Feb. 16, 1973 Found 3/4" steel bar P.Pole & T.Pole NW 42.45' P.Pole NE 60.91' T.Pole SE 33.70' P.Pole SW 47.28' C/L st. sign SE

CONTINUED OVER --L.C.R.C. Liber 3, Pg. 142 Jan. 3, 1977 PK in sde T.Pole NW 42.78' PK in sde T.Pole SE 44.03' PK in sde P.Pole ENE 61.43' Nail in sde 30" Maple NNE 73.43' C/L st. sign SE 38.9'

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-9 Found C.I.M. in Mon. Box in B.T. at intersection of 40th Ave. and Perry St. Found nail & bottle cap in SW sde P.Pole wires N-S-E-W N70°E 61.0' \$38°E 51.17' Found PK nail in SW sde P.Pole wires N-S Found PK nail in SW sde P.Pole wires E-W-S N70°W 42.78' Found PK in NW sde P.Pole wires N-S-E-W N70°E 61.51'

Accepted as a careful perpetuation of the position of the original corner.

P.A. 345 OTTAWA COUNTY

D.

PEER APPROVED

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-9 Corner common to Sections 19, 20, 29 and 30 Cast Iron Mon. in Mon. Box at intersection of 40th Ave. and Perry St. Set nail & O.C. tag in W'ly sde of 30" Maple N21°E 89.21' Set nail & O.C. tag in SE sde of P.Pole

Set nail & O.C. tag in SW sde of P.Pole

Set nail & O.C. tag in SW sde of P.Pole

Stenail & O.C. tag in SW sde of P.Pole

Systematical C/L "X" 40th Ave. and Perry St. 5' West and 6' South N70°E 61.45' S38°E 51.17' N70°W 42.78'



Date DEC. 12, 1994

Surveyor's Michigan License No. \_\_

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAN., 1983

L.C.R.C. Liber 5, Pg. 260 Aug. 28, 1986 Set C.I.M. PK in T.P. NW 42.78' PK in P.P. ENE 61.43' T.P. SE 33.98' P and T Pole NW 42.78' 30" Maple NE 73.55'