DEC 01 1998

Ottawa County Remonumentation

RECORDED

SECTION

LAND CORNER RECORDATION CERTIFICATE

98 MAY 22 PH 4: 06

orners in	Filing Requirement of Act 74, Mich. P.A. 1970
711010 111	


For co <u>Ottawa</u> Located In: Corner Code ## REGISTER OF DEEDS. T 6N R 13W A-7 (NW, 19) 1. Public Land Survey Georgetown Twp T _____ R ____ T____R_ T _____ R __ 2. Property Controlling _ T ____ R __ S ____ T ___ R _ in Section S ____ R ___ 3. Miscellaneous _ T _ Property in Sec. R

Register of Deeds Stamp & File Number

4.	. Lot No, Recorded Plat	
5	Private Claims	

John C. Bueche, in a field survey on March 12 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

Lucius Lyon, 1831 West Boundary 20 South of post

Set post cor. Secs. 18 & 19 Pine 28 N 38 E 22 Beech 6 S 13 E 38

LCRC L3, P80, April, 1976LCRC L1, P728, Nov., 1972 St. sign S 85 E 65.23' PP S 85 E 60.23'

NW cor. hse. footing

S 41 E 161.97' S end culvt. S 76 W 53.60'

TP N 40 W 71.75' 28" Oak N 30 W 71.65' Blendon cor. 13.17'

38" Oak N 25 W 71.55" S end culvt. S 70 W 53.70'

3/4" solid iron in mon. box

PP S 87 E 60.35'

<u>OVER</u>

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-7 Found 4" Harrison Mon. in Mon., Mon. is 0.10' East of East Line of Twp. M-7 (NE, 24) & M-8 (E14, 24) 6-14

As per above wit. & wit. on back

And is accepted as a careful and faithful perpetuation of the position of the original corner.

P.A. 345 OTTAWA COUNTY PEER APPROVED 4/20/98

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-7 4" Harrison Mon. in Mon. Box

Wit. are to point on Twp. Line

Ottawa Co. Remon, Tag & Nail in S side UP S 45° W 51.34' Ottawa Co. Remon. Tag & Nail in S side UP S 85° E 60.43'

Ottawa Co. Remon. Tag & Nail in SW side 38" Oak N 20° W 71.32' Ottawa Co. Remon. Tag & Nail in W side 10" Oak N 55° W 91.54'

Top of hydt, N 20° E 63.37' Biendon cor. M-7 North 13.25'

On C/L bit. N-S; on C/L bit. West & tree row East

JOHN C BUECHE LAND SURVEYOR

Signed by	John C	Buche
Signed by John Surveyor's Michig	i C. Bueche an License No.	,P.S. 13027
Our royor o minoring	MIII MINOCO 110	

SURVEY & REMONUMENTATION

DEC 01 1998

PART A - continued

SECTION

LCRC L5, P118, June, 1984 Fnd. ½" iron bar in MB set CIM PP E 60.33' 8" Pine NE 51.45' 30" Oak NNW 71.49' TP NW 71.72'

Exxel, 1992 notes Cl Mon. in Mon. Box PK in N side PP E 60.33' PK in SE side PP SW 51.36' Nail in SW side 20" Maple SE 88.77' Nail in SW side 36" Oak NW 71.48' Cor. for Sec. to W, N 13.25'

de 36" Oak NW 71.48"
to W, N 13.25'

M-7

GLO 20 (13.20')

Sec 24

Sec 19

M-8

M-9

GLO 19

GLO 19

GLO 19

REMON LIBER 4 PAGE 58