1993

OTTAWA COUNTY REMONUMENTATION

RECORDED

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

93 DEC 15 AM 9: 26

Fau 200-200 i-	riling Requirement of Act 74, Mich. P.A. 1970		, cos	de Reddoman
For corners in OTTAWA			نا مروحه به تا توسی کرای بلد. منابع و هم معمور	GISTER OF DEEDS
	Located In:	Corner Code ##	27 KC DT	TAWA COUNTY MI
(County)			_	
Public Land Survey	T 6N R 13W T R	C-5 (SE cor Section 7) Georgetown Twp	•	
	T R			
	T R			
	T R		egister of Deeds	Stamp & File Number
Property in Sec. S	T R			
4. Lot No, Recorde	ed Plat		- A B C D	EFGHIJKL
5. Private Claims	<u> </u>			
			2 6 5	
			3	
, Randai J. Vugteveen	Novemb	er 18 93	4 \- \frac{1}{2}\frac{1}{2} \frac{1}{2}	
do hereby certify that under requireme	neid survey on	, 19,	5	
in lines 1 and 2 above were in confor			6 18-17	-16151413
current manual of survey instructions	~	· ·	7	
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5			8 19 20	
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law: established, re-established, monumented, re-monumented, recovered, found as			9	
expressed below:	msneu, monumenteu, re-	-monamentea, recovered, lound as	10 30 29	28 27 26 25
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.			11	
			12 31 32	33 34 35 35
			13	
A. Description of original monum	ent and accessories ar	nd/or subsequent restoration:		
C-5 LCRC Liber 1, Page 603	C-5 LCRC Li	ber 2, Page 593		
Nail in side cor fence post SSE	1.20 / Found 1" Ir	on Bar		
Nail in side fence post N 57.61,		N 1_18'		
side 8" Oak ENE 69.65	•	oost SE 0.72'		
	Fence post	SSE 10.05'		
	l i	 		
	l I	; [
	i	i		
		applied in restoring or reestablishin ful and faithful perpetuation of the		ne
original corner				
Nail in side cor fence post SSE	•	N 1.18' laying down		
leaning South	•	post SE 0.72' leaning South		
Center 12" Oak ENE 69.5'	Fence post	SSE 10.05' laying down		

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: C-5 Cast Iron Monument

Found PK in W side 8" Elm N 43.18' | Found N&T in W side 6" Elm S3W 15.22' Found N&T in S side 10" Elm N45E 9.71'

Set Ottawa County Remon Tag & Nail in N side Triple 12" Oak NE 69.58' Set Ottawa County Remon Tag & nail in W side 8" Elm N 43.18' Set Ottawa County Remon Tag & Nail in corner fence post SSE 1.41'

Set Ottawa County Remon Tag & Nail in W side 6" Elm S3W 15.22'

Set Ottawa County Remon Tag & Nail in S side 10" Elm N45E 9.71'

Signed by _

28429 Surveyor's Michigan License No. __

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISEO MAY 14, 1975

UGTEVEEN

NO.

CO LAND SUR!