

APR 2 4 1005

For corners in

Ottawa County Remonumentation

RECORDED

94 DEC 15 AM 11: 53

## COMMISSION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Loly de Dudlina

Ottawa (County)		Located In:	Corner Code ##		G.		WA COU				
1. Public	Land Survey	T 7N R 13W T R R	G-7	1						•	
in Sect 3. Miscell	=	T R S T R S T R S T R S T R		-	gister of	Deeds	Stamp	& Fil	e Nu	mbe	er •
4. Lot No	, R	ecorded Plat			A 1	3 C D	ΕF	G H			, ,
	•				Ĥ	ŢŢ	<u> </u>	ΤΤ	$\dot{ o}$	֓֞֞֓֓֓֓֓֓֓֓֓֟֝֟֝֟֝֟֝ <del>֡</del>	ΓŤ
Mar	rice J.				2	5- 	- <del> -</del>	†-3 1	十	·2	
	sema		Oct. 19	94	4						
		, in a field survey on			5 1	T i	T i	Tï			
do hereby c	ertify that under rec	uirements of P.A. 74, Michigan P.	A. of 1970, the corner points r	mentioned	6	17	16-		$\perp$	14—	
		n conformance with regulations a actions of the United States Depa			7		<u> </u>			1	
Managemen	t or by a decree of a	a Court of Law and/or that the corr	ner points mentioned in lines	3,4 and 5	8	20			<u>:</u>	 -23	24
		in the rules of the Michigan Board e-established,monumented,re			9	_		1-1		Т,	$\square$
expressed t		e-established, monthinented, re	-monumented, recovered,	TOUTIO AS	10 3	029	28-		<u>-</u>	-26—	25
NOTE: No	ot more than 4 c	orners, all in the same town	and range, may be recor	ded	11					+	$\vdash \vdash$
or	this certificate.				123	132	33_	-34	<del>                                     </del>	-35	36
A. Descri	ption of original i	monument and accessories a	nd/or subsequent restor	ation:	13			1 1			II-
GLO - 1838	3 by	Nederveld - 1	975 per L.C.R.C.	Rosema	- 1985	per	L.C.R	., C.			
R. Whitcomb D.S.			P. 14 (over)	(over)		•					
Set post											
12" Beech	- N7 1/2°W	.28 ch. Jonker - 1978	per L.C.R.C.	Joiner	- 1990	) per	L.C.R	.C.			
6" Walnut - S17°W .25 ch. rec. in L. 3, P. 331 (over)				(over)							

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found C.I. mon. (top is at road grade) Found nail in SE. side Power pole - S56°W 100.80' Found nail in W. side 36" Maple - S6°E 195.25' Found nail in S. side 11" Locust - S87°E 34.44'

I hereby accept this corner as a correct and accurate perpetuation of the position of the original corner.

P.A. 345 OTTAWA COUN PEER APPROVE

G-7 Set nail and remon. tag in SE. side Power pole - S56°W 100.80° Set nail and remon. tag in W. side 36" Maple - S6°E 195.25' Set nail and remon. tag in S. side 11" Locust - S87°E 34.44' Set nail and remon. tag in SW. side 9" Locust - N42°W 74.92' On centerline of roads N., S., W.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: OF MICHIGAN MAURICE J. ROSEMA LAND SURVEYOR NO. 27459 ROFESSION

Dec. 10, 1994

Surveyor's Michigan

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REMON LIBER 2 PAGE 436

Part A - continued

Nederveld - 1975 per L.C.R.C. rec. in L. 3, P. 14

Bt. spike

Street sign - ESE. 16.3'

Nail in Power pole - Sw. 102.00'

Nail in 36" Maple - SSE. 194.75'

Jonker - 1978 per L.C.R.C. rec. in L. 3, P. 331 5/8" round iron
Nail in face of Power pole - SW. 100.57'
c.l street sign post - ESE. 18.0'
Spike in W. side 36" Maple - SSE. 195.2'
Nail on N. side Lucust clump - E. 27.38'

Rosema - 1985 per L.C.R.C. 5/8" round iron c/I street sign - E. 26.20' Nail in W. side 36" Maple - ESE. 195.39' Nail in face of Power pole - SW. 100.43' On centerline of gravels roads N.-S.-W.

Joiner - 1990 per L.C.R.C.
C.I. mon.
Nail in W. side 36" Maple - SSE. 195.39'
Nail in face of Power pole - SW. 100.43'
c/l steel pipe street sign - E. 26.20'
At c/l gravels roads N.-S.-W.

8888