RECORDED

99 OCT 27 PM 1:50

SECTION

Ottawa County Remonumentation LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

11000
Allen
ER OF DEEDS

For corners in				REGISTER OF DEEDS					
Ottawa	Located In: Corner Code #			ŊŦ.	AMP CO	1.13 Y,	111		
(County)									
1. Public Land Survey	T <u>7N</u> R <u>14V</u> TR TR	H-9 N 1/4 corner, Section 2 Allendale Township	7						
Property Controlling in Section Miscellaneous Property in Sec.	S TR S TR S TR S TR		Re	gister of De	eds Sta	mp & !	File Nı	umber	
4. Lot No, Reco	orded Plat		1 A	B C D E	F G	н :	ı J	к L	
J. 1 111410 Junio			2	65-	-∤- ┼	— 3 — 	2- 	+1	
Maurice J. Rosema	, in a field survey on _Au	igust 16 19 99 to hereby state tha	t under 4	7-1-8-	_9_	-10-	-11-		
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above trade conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented,			s of the 5 and /or 6 ichigan 7 nented,	19 17 10 10 20	_16-	—15— —15—	14	13	
recovered, found as expressed t	pelow:		• -						
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.			10	30 -29	28		26-	25	
			12	3132	33	34 	35		
	nonument and accessories a	and/or subsequent restoration:							
H-9 GLO - 1832 Britain D.S. Set post	LCRC per Liber 5, Page 551 (Rosema - 1984) (over)			CRC per Li onnema - : ver)		age 2	:95		
12" Sugar - N13°W 22 links 12" Lymm S38°E 23 links	LCRC per Liber 3, Pag (Campbell - 1978) (over)	ge 310	(R	LCRC per Liber 1, Page 511 (Roon - 1972) (over)					
~~ ^		od applied in restoring or reestablis		montatio	n can				
Found 1/2" re-rod in me	onument box, replaced i ace) of building - N50°V	ron rod with 3/4" x 2' steel ro V 100.50'	a win tenor	imikananu	ır cah				
				77.7°5 (c)	11.5	. 7			

perpetuation of the position of the original corner.


C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I hereby accept this corner as a correct and accurate

3/4" x 2' steel rod with remonumentation cap in monument box Set nail and remonumentation tag in E. side Power pole - N27°E 58.02' Set nail and remonumentation tag in E. side Power pole - S33°W 62.62' Set nail and remonumentation tag in N.-S. conc. sidewalk - S15°E 89.49' Center of top of hydrant - N52°W 55.34'

SW. building corner - N48°E 152.76 SE. corner brick building - N50°W 100.50°

Signed by _ Surveyor's Michigan License N Date September 11, 1999



URITHE LATERA

SECTION
LCRC per Liber 1, Page 511
(Roon - 1972)
No point in place
Comer is 0.17' S of 0.78' E. of center of monument box
NW. corner of store - SE. 48.00'
NE. corner of station - SW. 59.12'
SW. corner of conc. sign base - NE. 49.42'

LCRC per Liber 2, Page 295 (Bonnema - 1973) ½" iron NW. corner of block building - SE. 48.60' NE. corner gas station - SW. 58.49' Nail in side P. pole - NNE. 58.52'

LCRC per Liber 3, Page 310 (Campbell - 1978) 3/8" re-rod NW. corner brick building - S42°E 48.62' NE. corner nearest building - S37°W 58.55' SE. building corner - N49°W 99.93' Power pole - N29°E 58.50'

LCRC per Liber 5, Page 151
(Rosema - 1984)
½" re-rod in mon. box
top of SW. bolt at base of sign - NE. 51.80'
NE. corner brick gas station - SW. 58.72'
SE. corner casting of catch basin - NNW. 53.24'