Ottawa County Remonumentation

RECORDED

LAND CORNER RECORDATION CERTIFICATE

	Filing Requiren	nent of Act 74, Mich. P.A. 1	970 36 HEL 18 PM 4: 56
For corners in			The die Olderan
Ottawa (County)	Located In:	Corner Code ##	REGISTER OF DEEDS
A D. I. Callanda Complex	T T7N RR14W	1-8	OTTAWA COUNTY, MI
Public Land Survey	T R	(El cor.	•
	T R	Sec. 22)	
	T R		
2. Property Controlling in Section	S T R S T R		
3. Miscellaneous	S T R		Register of Deeds Stamp & File Number
Property in Sec.	S T R		
4. Lot No , Recorded Plat A B C D E F G H I J K L M			
			A B C D E F G H 1 J K L M
			2 6 5 4 3 2 4 3
			4 7 8 9 10 11 12
Maurice J. Rosema	in a field survey on Oct. 11	. 19	5
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the			
current manual of survey instructions of the United States Department of the Interior, Bureau of Land			
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a			
Court of Law; established, re	e-established, monumented, re-mo	onumented, recovered, found as	
expressed below.			10 30 29 28 27 26 25
NOTE: Not more than 4 co on this certificate.	orners, all in the same town and	range, may be recorded	12 31 32 33 34 35 36
Off this permittant			13
A. Description of original n	monument and accessories and/	or subsequent restoration:	
GLO - 1832 by Noah	Brookfield L.C.R.C. r		.C.R.C. recorded in
for Calvin Britain D.S. 1, page 441 - June 9, 1972 Liber 4, Page 217 - Sept. 23,			
10" Sugar S39°E 9 lks (over) 1981 10" Beech N19°W 22 lks. L.C.R.C. recorded in Liber 5, (over)			
10. Beech Mia. M 22	Page 149 -	Aug. 1, 1984	OVOE ,
	(over)	•	
		•	4
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:			
т Q			
Found C.I. mon. 1.7' deep with capped rerod #27459 above it, replaced rerod with 3/4" X 1' steel rod with 0.C. cap			
Found nail in NW si		SW 49.40'	
Found nail in S sid	de 18" Sassafrass	W 51.57'	P.A. 345 OTTAWA COUNTY
Found nail in NE si	ide 26" Maple	SE 28.34' SSE 66.16' PEE	R APPROVED 12-9-94
Found nail in W sic	de 24° mapte	DDE 00+10 FEL	A I I I I I
		1	402/
I hereby accept this corner as a correct and accurate perpetuation of the position of the original corner.			
perpecuacion of the position of the original collective.			
			•
C. Description of monume	ent for corner and accessories e	stablished to perpetuate locat	ing the position of the corner:
I-8	•		TE OF MICH.
3/4" X 1' steel ro	d with O.C. cap above (C.I. mon. s69°W 39.40	STA
Set nail and O.C.	tag in NW side P pole tag in S side 18" Sass		
Set nail and O.C.	tag in NE side 26" Map	le S52°E 28.34	ROSEMA
Set nail and O.C.	tag in W side 24" Mapl	e S15°E 66.16	LAND * SURVEYOR C
On tree row to W		w 1'	NO. 27459
Centerline of N-S	graver road	AA 1	SURVEYOR NO. 27459
			ROFESSIONAL
i	_ ^		WWW. WOLLAND
	min S Tours	Date0	ct. 21, 1995
Signed by	aug .		
Surveyor's Michigan Licens	se No		RM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISEO MAY 14, 1975
			REVISED JAN., 198:

I-8, T7N, R14W

L.C.R.C. recorded in Liber 1, Page 441
- June 9, 1972
3/4" Pipe
Nail in face of 17" Maple SE 27.34'
Nail in face of Power pole SW 39.13'
Nail in face of 13" Sassafrass W 20.53'

L.C.R.C. recorded in Liber 4, Page 217 - September 23, 1981 Cast Iron Monument

Power Pole SW 39.46'
18" Sassafras W 52.18'
26" Maple SE 28.28'
24" Maple SSE 66.68'

L.C.R.C. recorded in Liber 5, Page 149
- August 1, 1984
C.I. Monument
Nail in NW side P.pole SW 39.45'
Nail in NE side 26" Maple SE 28.35'
Nail in S side 18" Sassafras W 52.24'
Nail in W side 24" Maple SSE 66.80'