FEB 2 4 2000

SECTION

For corners in

## OTTAWA COUNTY REMONUMENTATION PROGRAM **LAND CORNER RECORDATION CERTIFICATE** Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

99 DEC -2 PM 1: 13

Corner Code #C-8

**OTTAWA** Located in: ROBINSON 1. Public Land Survey **T7N R15W** W174 of Sec. 20 R 2. Property Controlling in Section R Miscellaneous Property in Sec.

Register of Deeds Stamp & File Number

, Recorded Plat \_\_ 4. Lot No. 5. Private Claims

I, Robert E. Lemke, surveyor, in a field survey on Sep. 8, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, reestablished, monumented, recovered, found as expressed below:

Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

SEE BACK OF SHEET FOR CORNER HISTORY

В ĸ L M

PARKEL JULIO DE LA Miles emisored 9/13/99

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 4" DIAMETER CAST IRON MONUMENT IN MONUMENT BOX 12" BELOW GRADE AT THE INTERSECTION OF RICH STREET AND  $136^{TH}$  AVE.

8) FOUND 11" RED PINE

AND MEASURED 63.4' S.W. FACE OF TREE AND MEASURED 48.2'

7) FD P. POLE 6) FD 29" OAK

NE SE

5) FOUND NAIL IN 12" WHITE PINE SW

AND MEASURED 60.45' AND MEASURED 60.80'

And is accepted as a careful and faithfulperpetuation of the position of the original corner

-C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

•C-8 CAST IRON MONUMENT IN MONUMENT BOX.

SET NAIL AND OTTAWA COUNTY REMON. TAG IN S.W. FACE OF 11" PINE N 50°E 63.35' (1.4') ABOVE GRADE "SET NAIL AND OTTAWA COUNTY REMON. TAG IN S.W. FACE OF POWER POLE N 70° E 48,27' (2') ABOVE GRADE SET NAIL AND OTTAWA COUNTY REMON. TAG IN NORTH SIDE OF 32" OAK S 45°E 60.61' (11) ABOVE GRADE SET NAIL AND OTTAWA COUNTY REMON. TAG IN N.E. FACE OF 12" WHITE PINE S 50°W MONUMENT IS AT THE INTERSECTION OF RICH STREET AND 136<sup>TH</sup> AVE. 60.80' (4') ABOVE GRADE

For SDI CONSULTANTS, LTD

Date <u>9-20-/99</u>

Surveyor's Michigan License No. 40160



SEE BACK

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995

## FEB 2 4 2000

## SECTION

## OTTAWA COUNTY ROBINSON TOWNSHIP TOWN 7 NORTH, RANGE 15 WEST

C-8

A. Description of original monument and accessories and/or subsequent restoration

-G.L.O.

40.00 SET 1/2 MILE POST

BEECH 10 N63E 37 DO 10 S63W 23

-JOHN CLAPP, RECORDED L.C.R.C. LIBER 1 PAGE 179 DATED: 11-30-1971 FOUND IRON

| 1. | NAIL IN FACE OF 10" PINE  | NE | 45.35' |
|----|---------------------------|----|--------|
| 2. | NAIL IN FACE OF 24" OAK   | SE | 60.75  |
| 3. | NAIL IN FACE OF TEL. POLE | sw | 44.27' |
| 4. | NAIL IN FACE OF ST. SIGN  | SE | 43.70' |

-THOMAS JOINER, RECORDED L.C.R.C. LIBER 3 PAGE 231 DATED: 11-14-1977 IRON, FOUND ½" PIPE USING OLD TIES RECORDED(AS SHOWN ABOVE) SET CAST IRON MONUMENT INSCRIBED "OTTAWA COUNTY SECTION CORNER."

 5. SET NAIL & TIE TAG IN 8" WHITE PINE
 SW 60.91

 6. SET NAIL & TIE TAG IN 29" OAK
 SE 60.63

 7. SET NAIL & TIE TAG IN P. POLE
 NE 48.12

 8. SET NAIL & TIE TAG IN 6" RED PINE
 NE 63.40