## SURVEY & REMONUMENTATION

APR 2 4 1995

4. Lot No. \_

Private Claims \_

RECORDED

## COMMISSION

OTTAWA COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

94 DEC 15 AM II: 50

Filing Requirement of Act 74, Mich. P.A. 1970 Selvedis Caleman For corners in REGISTER OF DEEDS OTTAWA COUNTY, MI

Ottawa Located In: Corner Code ≠# (County) Robinson Twp. T 7N R15W K-5 1. Public Land Survey NW Corner T \_\_\_\_\_ R \_\_\_\_ T \_\_\_\_\_ R \_ Section 13 \_\_\_ R Property Controlling T R in Section S \_ ... T \_ R 3. Miscellaneous \_ T \_\_\_\_ R \_ Property in Sec.

Register of Deeds Stamp & File Number

I Carl P. Englert, in a field survey on November 22 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5

\_\_\_, Recorded Plat \_\_\_

above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration:

24 Links

4 Links

K-5 corner common to Sections 11,12,13 & 14 LCRC Liber 1, Page 659 (10/72)

Set Cast Iron Monument

10

Nail in Face of 8" Tw. Oak SW

Nail in Face of T.P. 147.05 SSW

Nail in Face of P.P.

SE 126.91

128.07

5' West of & 104th Ave.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K-5 corner common to Sections 11,12,13 & 14

Found broken Harrison Cast Iron Mon. in Mon. Box 6" Deep 5'+/- W. of & Road

Found P.P. SE 126.91' ( No Nail )

Original Gov't corner set May 1832

S670E

by Calvin Britain D.S.

Set Corner

Beech 10"

Hemlock 15" N42°W

Found 16" TW Oak SW 128.07' ( No Nail )

PALOIS OTTAWA COUNT

PEER APPROVED 10 1/2

Accepted as a careful and faithful perpetuation of the original position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-5 corner common to Sections 11,12,13 & 14

4" Harrison Cast Iron Mon. in Mon. Box (broken top)

S360E 127.57' O.C. Remon. Tag & Nail in N.E. side P.P. O.C. Remon. Tag & Nail in N.W.side 16" Tw Oak S41°W 128.26'

29.571 O.C. Remon. Tag & Nail in N. side P.P. West

N16°E 270.05' O.C. Remon. Tag & Nail in W. side P.P.

Carl P. Englatf Surveyor's Michigan License No.

CARL P. ENGLERT JR. **PROFESSIONAL** 

William AMENISER

FORM APPROVED BY MICHIGAN STATE BO