## SECTION

## OTTAWA COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

99 SEP 23 PM 3: 21

For corn	ers in	'	i iiiig reoqui	icinoik of Ac	· · · · · · · · · · · · · · · · · · ·	A. 1970		A	00.00	-
0.	ttawa	Located in:	Co	rner Code #				REGISTED	Title Con OF DEEDS	
	(County)	Crockery						OTTAWA	AL DEEDS	`
1. Public	c Land Survey	T <u>8N</u> T T	R15W R R R	B-1 N 4 corr Sec. 6	<u>ier</u>					
in Se		S T S T	R R	<u></u>	<del></del>					
	ellaneous erty in Sec.	S T	_R	····						
Flope	erty in Sec.	<u></u> ا			<b></b>		Register	of Deeds Sta	mp & File N	lumber
4 1 at N	o Boord	lad Diat								
4. LOUN 5. Privat	o, Record te Claims	led Plat				, 1 r	<u> </u>	D E F G	ніј	KLM
			•			2	-6	54	-32-	
. Comi	D Prelout		c (a o			3		+++		
requireme	P. Englert nts of P.A. 74, Michigan	P.A. of 1970, the	corner points n	rentioned in lines	1 and 2 above we	ere in _	- <del>7</del>	8 9	10-11-	12-
conformar	nce with regulations and rates Department of the In	ules therefore as re	quired in the cu	rrent manual of so	arvey instructions of	of the 5	10	17 16	15 14	
that the c	orner points mentioned in Land Surveyors or by	n lines 3, 4 and 5 al	bove were in co	nformance with th	e rules of the Mich	higan _ i	18			13
	found as expressed before		uit of Law, es	iauisiieu, ie-esia	ioisnea, monume	int <b>e</b> a, 8  -	19	20-21-	_2223	24
NOTE:	Not more than 2 corners, all in the same town and range, may be recorded					9			<del>-   -     -</del>	-
	on this certificate.					10	_30	2928	-2'72'6-	2 <sup>1</sup> 5
						11	1		1   1	
						12		32 33	35	36
A. Desc	ription of original mon	ument and acce	ssories and/o	subsequent re	storation:	10				
	John Mullett Set 1/4 Sect Elm 20" N14° Elm 6" NW 3.	ion Post E 71 Lin	(S	LCRC Lib Muskegon Found 1" WSW 42.2 SE 71.2	er 1001, Co. Rec	Page ords B sh aple	451 Er	nglert	Ţ	
B. Des	cription of corner evide	ence found and/o	or method app	olied in restoring	or reestablishin	ng corner:				
B-1	Found 4" Har Found 26" Ma Found 16" Ma Found 24" Ma	aple NW 7 aple NW 4	1.42' 2.35'	Monument	in Nort	h Bank	of C	reek		
	This Monumer position of			the bes	t availa	ble ev	idence	e of the	:	
								9/17	/99	
C. Desc	ription of monument fo	or corner and acc	cessories esta	blished to perp	etuate locating t	he position	of the cor		クラ	<b>&gt;</b> ````
B-1	4" Harrison O.C. Remon. O.C. Remon. O.C. Remon. Q.C. Remon. G.C. Remon.	Tag and I Tag and I Tag and I	Nail in Nail in Nail in	West Sid North Si North Si	de 16" M de Twin	aple 10" El	N75 m S70	°W 71.42 °W 42.39 °E 13.89 °E 71.16	5 ' ) '	Receipt #5
	B-1, T8N, R1	5W, held	as comm	on to B-	13, T9N,	R15W.		25 -7 1	CARL P. ENGLERT JR. ROFESSIONA	CZ.
Signed b	y <u>Caul F</u> 's Michigan License N	Engles o.	189	987	Date _	9/13	19	9 P. C.	SURVEYOR No. 18987 ONAL S	SOAS RECEIFT
				F	ORM. APPROVED BY	MICHIGAN STA	ATE BOARD C	F PROFESSIONAL	SURVEYORS	JAN, 285
			Liber 4						REVISED REVISI	MAY 14-197! DJAN, 498: D OCT., 199:

FEB 2 4 2000

SECTION

B-1 T8N, R15W
LCRC Liber 1056, Page 573 Recorded as B-13 T9N, R15W,
Muskegon County Records
John Clapp April 1975
Found Iron Pipe from Ottawa County Surveyors ties
12" Maple N75°W 12.11'
18" Maple N10°W 71.67'
28" Oak S40°W 61.96'
18" Maple South 71.20'

LCRC Liber 4, Page 33 Kirk Van Order 1980
Found 1" Iron Pipe, set Cast Iron Monument inscribed
"Section Corner"
12" Maple NW 42.14'
18" Maple NW 71.67'
28" Oak SW 61.96'
18" Maple S 71.20'

TAN, RISW

Section 31

A-13

B-13

C-13

B9°33'30"

B9°23'30" 2664.12' B9°12'55" 2656.0B'

C-1

N Section 6

TBN, RISW